Y52 Emergency Stop SOP (Document ID: SOP-Y52-ESTOP, Rev.B)

Status: SUPERSEDED - Do NOT use for active operations

Procedure: Press red Mushroom button E-STOP. Engage mechanical disc brake immediately with full deceleration rate 12 m/s^2.

Warning: Rev.B mechanical full-brake command was found to cause strip breakage hazard and is replaced by Rev.C.