
MIT OpenCourseWare http://ocw.mit.edu

2.007 Design and Manufacturing I Spring 2009

For information about citing these materials or our Terms of Use, visit: http://ocw.mit.edu/terms.



Attach magnets as shown

SCALE 1.000