QUALITY & SAFETY INSPECTION REPORT: INSP-7211

Site: Powai Plant 1 Machine Shop | **Date:** 2026-04-19
Certified Auditor: Anand Varma (Senior Mechanical Auditor)

Checklist Inspection Item	Evaluation	Inspector Remarks
Visual inspection of casing for hairline casting cracks	PASS	Zero defects detected under UV dye
Dynamic shaft runout balance check (<0.02mm)	PASS	Measured at 0.012mm TIR
Hydrostatic pressure containment hold (350 bar / 30 min)	PASS	Pressure maintained without drop
Mechanical seal leak rate within tolerance (<5 ml/h)	PASS	No visible dripping observed
Foundation anchor bolt torque verification (450 Nm)	PASS	Torqued and calibrated
Emergency automatic shutdown circuit trip response	PASS	Tripped in 180ms
Bearing vibration velocity RMS (<2.8 mm/s)	FAIL	Normal

Deficiencies Identified: Vibration spike on drive end bearing journal exceeding ISO 10816 limits
Corrective Actions: Re-align coupling hubs and replace drive-end bearing spacer
Next Scheduled Inspection: 2026-10-26