

BP394/832 MBL

Jun 2, 2026

Total # of Issues: 50



List/Report Name
BP394/832 MBL

Project Name
First Punch

Company Name

Date
Jun 2, 2026

Project Number

Consultant Name

Total # of Issues 50

Sign Off:

Issue #
1

Issue
Touch up all shoe nail holes for cab shoe at bathrooms and kitchen

Floor

Room

Comment

Sheet

Status
■ Incomplete

Assign To
Aristokraft

Resolution Date

Issue #
2

Issue
Touch up face frame guest hall bath with fill stick and touch up pen

Floor

Room

Comment

Sheet

Status
■ Incomplete

Assign To
Aristokraft

Resolution Date



Issue #
3

Issue
Scribe bowing right side guest hall bath

Floor

Room


Comment

Sheet

Status
■ Incomplete

Assign To
Aristokraft

Resolution Date



Scan me

POWERED BY



Punch List

Download on the App Store


Issue # 4	Issue Install corner mold and middle scribe at island had to remove for flooring install, in site in box
Floor	
Room	
Sheet	Comment
Status ■ Incomplete	
Assign To Aristokraft	Resolution Date

Issue # 5	Issue Skin starting to delaminate left end of section at fridge opening	
Floor		
Room		
Sheet	Comment	
Status ■ Incomplete		
Assign To Aristokraft	Resolution Date	


Issue # 6	Issue Toe kick overcut at island	
Floor		
Room		
Sheet	Comment	
Status ■ Incomplete		
Assign To Aristokraft	Resolution Date	

Issue # 7	Issue Touch up right side of faceframe looking to back door	
Floor		
Room		
Sheet	Comment	
Status ■ Incomplete		
Assign To Aristokraft	Resolution Date	


Issue # 8	Issue Level all doors and drawers	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Aristokraft	Resolution Date	
Issue # 9	Issue Touch up lower left of sink	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Aristokraft	Resolution Date	
Issue # 10	Issue Clean up around all handles, wood material showing	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Aristokraft	Resolution Date	
Issue # 11	Issue Remove sticker off under side of upper cabs	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Aristokraft	Resolution Date	

Issue # 12	Issue Touch up face frame left of microwave	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Aristokraft	Resolution Date	

Issue # 13	Issue Seam crown better	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Aristokraft	Resolution Date	

Issue # 14	Issue Lower skin issue right cabinet beside microwave	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Aristokraft	Resolution Date	

Issue # 15	Issue Touch up face upper cab left of sink	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Aristokraft	Resolution Date	

Issue # 16	Issue Corner of face frame delaminating right upper beside sink	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Aristokraft	Resolution Date	
Issue # 17	Issue Fix miss drill upper above dishwasher	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Aristokraft	Resolution Date	
Issue # 18	Issue Adjust t strips to all carpet lipping and showing gap	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To BWF	Resolution Date	
Issue # 19	Issue Parge front left corner of entry way	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Charleston concrete	Resolution Date	

Issue # 20	Issue Parge crack right rear elevation.	
Floor		
Room		
Sheet	Comment	
Status ■ Incomplete		
Assign To Charleston concrete	Resolution Date	

Issue # 21	Issue Additional nails needs right side of garage trim lower	
Floor		
Room		
Sheet	Comment	
Status ■ Incomplete		
Assign To Coastal Exterior	Resolution Date	

Issue # 22	Issue Garage fascia metal is wavy, causing garage seal to be wavy	
Floor		
Room		
Sheet	Comment	
Status ■ Incomplete		
Assign To Coastal Exterior	Resolution Date	


Issue # 23	Issue Repair gouges in post front porch far right	
Floor		
Room		
Sheet	Comment	
Status ■ Incomplete		
Assign To Coastal Exterior	Resolution Date	


Issue # 24	Issue Touch ups need at poor cut top of garage trim	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Coastal Exterior	Resolution Date	

Issue # 25	Issue Seal whip at tankless	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Coastal Exterior	Resolution Date	

Issue # 26	Issue Poor cuts/damaged trim at garage door left side	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Coastal Exterior	Resolution Date	

Issue # 27	Issue Caulk touch ups at tops of front porch post	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To GTM	Resolution Date	


Issue # 28	Issue Paint touch up nail holes at front windows	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To GTM	Resolution Date	
Issue # 29	Issue Clean washed off paint off right right front hose bib	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To GTM	Resolution Date	
Issue # 30	Issue Paint sides of PDS and second coat of PDS	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To GTM	Resolution Date	
Issue # 31	Issue Try to remove paint overspray off scribe at guest hall bath	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To GTM	Resolution Date	

Issue # 32	Issue Caulk void touch up at middle left bedroom window	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To GTM	Resolution Date	
Issue # 33	Issue Remove paint over spray off left end of cabinets at fridge opening	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To GTM	Resolution Date	
Issue # 34	Issue Fully install dishwasher	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To NWP	Resolution Date	
Issue # 35	Issue Window over kitchen stuff and hard to operate please adjust	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To PBS	Resolution Date	

Issue # 36	Issue Window in Eat in area stiff and hard to operate please adjust
Floor	
Room	
Sheet	Comment
Status ■ Incomplete	
Assign To PBS	Resolution Date

Issue # 37	Issue Right window in living area squealing when operating please adjust	
Floor		
Room		
Sheet	Comment	
Status ■ Incomplete		
Assign To PBS	Resolution Date	

Issue # 38	Issue Right window in owners bedroom difficult to operate
Floor	
Room	
Sheet	Comment
Status ■ Incomplete	
Assign To PBS	Resolution Date

Issue # 39	Issue Silicone touch ups needed at tops to cabinets hall bath	
Floor		
Room		
Sheet	Comment	
Status ■ Incomplete		
Assign To Real deal	Resolution Date	

Issue #

40

Floor

Room

Sheet

Status

■ Incomplete

Assign To

SE Garage Door

Issue

Garage trim/seal needs more nails, dipping in places across the top

Comment

Resolution Date



Issue #

41

Floor

Room

Sheet

Status

■ Incomplete

Assign To

SE Garage Door

Issue

Right side of garage trim/seals needs another nail

Comment

Resolution Date



Issue #

42

Floor

Room

Sheet

Status

■ Incomplete

Assign To

Smiths

Issue

Seal not properly installed

Comment

Resolution Date



Issue #

43

Floor

Room

Sheet

Status

■ Incomplete

Assign To

Smiths

Issue


Foam gaps where lineset comes through

Comment

Resolution Date



Issue # 44	Issue House numbers are slanted, please install straight	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Stier Supply	Resolution Date	
Issue # 45	Issue Light pads needed at front entry door	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Stier Supply	Resolution Date	
Issue # 46	Issue T-support short cut at rear patio door	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Stier Supply	Resolution Date	
Issue # 47	Issue Adjust all doors to sit tightly in catches	
Floor		
Room	Comment	
Sheet		
Status ■ Incomplete		
Assign To Stier Supply	Resolution Date	

Issue # 48	Issue Defective hinges middle left bedroom. Replace all 3 look like the photo	
Floor		
Room		
Sheet	Comment	
Status ■ Incomplete		
Assign To Stier Supply	Resolution Date	

Issue # 49	Issue Hole for lower pin of double doors over drilled causing door to move and rattle and not seal tight		
Floor			
Room			
Sheet	Comment		
Status ■ Incomplete			
Assign To Stier Supply	Resolution Date		

Issue # 50	Issue Lower hinge defective owners bathroom door	
Floor		
Room		
Sheet	Comment	
Status ■ Incomplete		
Assign To Stier Supply	Resolution Date	