APPENDIX A: Connections

SMT32 evaluation:

NUCLEO-L010RB TMC-6300-BOB BREAKOUT BOARD

RACESTAR 0703 MOTOR

1S (3.7V) BATTERY

NC - NOT CONNECTED

| UH | PA7 |
|------------|--------------------------|
| UL | PB6 |
| VH | PC7 |
| VL | $\overline{\text{PB10}}$ |
| WH | PB4 |
| WL | PB3 |
| U | MOTOR PIN1 |
| H | MOTOR PIN2 |
| L | MOTOR PIN3 |
| GND | BAT- |
| GND | BAT- |
| GND | BAT- |
| GND | BAT- |
| +VBAT | BAT+ |
| VIO/STDBY | 3.3V |
| DIAG | NC |

RP2040 EVALUATION:

RP2040 BREAKOUT BOARD

TMC-6300-BOB BREAKOUT BOARD

RACESTAR 0703 MOTOR

<mark>1S (3.7V) BATTERY</mark> MPU6050 BREAKOUT BOARD

NC - NOT CONNECTED

| UH | GP10 |
|--------------------------|-------------------|
| UL | GP11 |
| VH | GP12 |
| VL | GP13 |
| WH | GP14 |
| $\overline{\mathrm{WL}}$ | GP15 |
| U | MOTOR PIN1 |
| H | MOTOR PIN2 |
| L | MOTOR PIN3 |
| GND | BAT- |
| GND | BAT- |
| GND | BAT- |
| GND | BAT- |
| +VBAT | BAT+ |
| VIO/STDBY | 3.3V |
| | |

NC

VCC 3.3V **GND GND SCL** GP5 **SDA** GP4

DIAG