

XTERIA
design
PANELS




PANELS

Montta Panels are relatively new generation of cementitious material with very high strength & durability. Concrete has become one of the materials of choice for Architects. Concrete has minimalistic style and can make things inherently impressive.

Our new collection also has a range of earthy colors with antique effects, in line with the international trends. we develop unique finishes, on request, for challenging projects.



Plank



Roma

600 mm

1200 mm

25 mm

600mm




Milano



Screws

670 mm



600 mm

Thickness - 12 mm




Multirib



Thickness - 12 mm

Beton



300 mm

1200 mm

Thickness - 12 mm

Beton



Thickness - 12 mm

Plank - Rust

600 mm

1200 mm

Thickness - 12 mm



Screws - Rust

600 mm



670 mm

Thickness - 12 mm



HANDLING THE PANELS

- The panels must be handled **vertically by their edges**
- Be careful **not to bend the panels**
- Warning: the **angles and edges of the panels are fragile.**




One person can transport a panel.
However, for safety reasons, it is recommended that two people carry it.

- Panels shorter than 2700 mm must be carried **by 2 people**.
- Panels longer than 2700 mm must have a **third person** to support the centre of the panel.

INSTALLATION

WEAR **GLOVES** TO
AVOID STAINING
THE PANELS



USE A SUITABLE
ADHESIVE



ALWAYS
HANDLE
THE PANELS
BY **THEIR EDGES**



DRILL AND CUT
ONLY WITH
DIAMOND TOOLS

REMOVE DUST
FROM THE PANELS
BEFORE AND AFTER
INSTALLATION



DO NOT USE
ADHESIVE
STRIPS ON THE
PANEL CLADDING

**Size:**

Variation of 1% can be expected in the dimension of the Montta panels. For appropriate alignment of the panels during installation, use of spacers is highly advised.

Thickness:

Variation of 10% can be expected in the thickness of the Montta panels.

Cracks:

Visible cracks on the panels are considered as defects caused with improper handling while storing or transportation. Hairline cracks on the panels are NOT considered to be defects. They are a natural characteristic of the material and do not tamper with the functionality. These cracks which are developed over the years are minute, surficial and generally not visible to the naked eye.

Pinholes and Air Bubbles:

Concrete naturally has some air trapped in it while manufacturing. The occurrence of holes / bubbles is an inherent attribute of the material. Therefore no panels are imitable.

Smooth Natural:

The Montta panels with this texture is one of our most sophisticated yet earthy offerings. You can expect a few small pinholes on the surface of the panel. This is not considered a defect.



Easy Application



Water, Algae & Fungus Resistance



UV Resistant



Endurance & Long Lasting



High Adhesion



Stain Resistant & Easy Clean

Disclaimer

Products may vary in colour from Photos, due to Print Quality.
We advise you to examine the actual products before Ordering.

ph no: 90374 54077
web : www.xteriadesign.com
Email: sales@xteriadesign.com