

---

```
clear,clc
k=1.2;
A=15;
L=0.25;
T1=600;
T2=50;
Q=(k*A*(T1-T2))/L;
fprintf('Heat Loss Q = %.2f W \n', Q);
```

*Published with MATLAB® R2026a*