TAYLOR, JARED 43-15S2-24R



State Farm
P.O. Box 106169
Atlanta, GA 30348-6169
Fax: 1-844-236-3646
statefarmfireclaims@statefarm.com

# **Structural Damage Claim Policy**

When you have a covered structural damage claim to your real property, you should know:

- We want you to receive quality repair work to restore the damages to your property.
- We will provide you with a detailed estimate of the scope of the damage and costs of repairs. Should the contractor you select have questions concerning our estimate, they should contact your claim representative directly.
- Depending upon the complexity of your repair, our estimate may or may not include an allowance for general contractor's overhead and profit. If you have questions regarding general contractor's overhead and profit and whether general contractor services are appropriate for your loss, please contact your claim representative before proceeding with repairs.
- There may be building codes, ordinances, laws, or regulations that affect the repairs of your property. These items may or may not be covered by your policy. Please contact your claim representative if you have any questions regarding coverage which may be available under your policy.
- If you select a contractor whose estimate is the same as or lower than our estimate, based on the same scope of damages, we will pay based upon their estimate. If your contractor's estimate is higher than ours, you should contact your claim representative prior to beginning repairs.
- State Farm® cannot authorize any contractor to proceed with work on your property. Repairs should proceed only with your authorization.
- State Farm does not guarantee the quality of the workmanship of any contractor or guarantee that the work will be accomplished within any specific time frame.
- It is understood that the contractor is hired by you, our insured, and that they work for you not State Farm.

If you have any questions or need additional information regarding your claim, please contact your claim representative immediately.

Date: 2/5/2021 11:32 AM 132214.1 06-18-2009 Page: 1



# **Building Estimate Summary Guide**

This summary guide is based on a sample estimate and is provided for reference only. Please refer to the estimate for specifics of your claim.

	Sta	te Farm In	surance				
Insured:	Smith, Joe & Jane		Estimate:	00-0000	-000		
Property:	1 Main Street		Claim number:	00-0000	-000		
	Anywhere, IL 0000	0-0000	Policy Number:	00-00-00	00-0		
Type of Loss:	Other		Price List:	ILBL8F_	MAR 13		
Deductible:	\$1,000.00			Remode F = Factor			
	Sui	mmary for	Dwelling				
Line Item Total	1				5,953.10		
Material Sales Ta	⊒ ax	@	10.000% x 1,520.00				
Subtotal				1	6,105.10		
General Contract	tor Overhead 2	@	10.0% x 6,105.	10	610.51		
General Contract	tor Profit	@	10.0% x 6,105.	10			
Replacement Co	st Value (Including G	Seneral Contrac	ctor Overhead and Pro	ofit 3	7,326.12		
Less Depreciatio		(832.50)					
Less General Co	ntractor Overhead &	Profit on Reco	verable &				
Non - recoverable	e Depreciation				(166.50)		
Less Deductible	5						
Net Actual Cash	Value Payment 6						
Max	imum Additio	nal Amoun	its Available If	Incurre	d:		
Total Line Item D	epreciation (Includin	g Taxes) 4	832.5	50			
Less Non - recov	erable Depreciation	(Including Taxe	s) [7]				
Subtotal				312	.50		
General Contract	tor O&P on Deprecia	ition	166.	50			
Less General Co	ntractor O&P on No	n - recoverable	Depreciation				
Subtotal							
Total Maximum A	Additional Amounts A	vailable If Incu	rred 8				
Total Amount of	Claim If Incurred 9						
Olain D	-10						
Claim Represent							
ALL AMOUNTS	PAYABLE ARE SU	BJECT TO THI	E TERMS, CONDITIO	NS AND L	IMITS OF		

- 1. Line Item Total Total value of all line items in the estimate plus possible adjustments for labor minimums. Labor Minimum is to cover a certain minimum number of hours for drive-time, set up time and applicable administrative costs and repairs.
- 2. General Contractor's Overhead and Profit - General contractor's charge for coordinating your repairs.
- 3. Replacement Cost Value (RCV) -Estimated cost to repair or replace damaged property.
- 4. Depreciation The decrease in the value of property over a period of time due to wear, tear, condition, and obsolescence. A portion or all of this amount may be eligible for replacement cost benefits.
- 5. Deductible The insurer will pay for losses, up to the policy limits, in excess of your applicable deductible.
- 6. Net Actual Cash Value Payment (ACV) - The repair or replacement cost of the damaged part of the property less depreciation and deductible.
- 7. Non Recoverable Depreciation -Depreciation applied to items that are not eligible for replacement cost benefits.
- 8. Total Maximum Additional Amount if Incurred - Total amount of recoverable depreciation after actual repair or replacement of the property.
- 9. Total Amount of Claim if Incurred -Total amount of the claim, including net actual cash value payment and total maximum additional amount available if incurred.

1002989 Date:

YOUR POLICY.

2/5/2021 11:32 AM Page: 2

### **State Farm**

TAYLOR, JARED 43-15S2-24R

Restoration/Service/Remodel

Insured: TAYLOR, JARED Estimate: 43-15S2-24R
Property: 500 BORDEAUX SQ Claim Number: 4315S224R
IRVING, TX 75038-7259 Policy Number: 58EUJ3644

Home: 817-545-4530 Price List: TXDF28\_APR20
Cellular: 817-793-5178 Price List: TXDF28\_APR20

Type of Loss: Hail
Deductible: \$2,760.00
Date of Loss: 4/19/2020

2/3/2021

Date Inspected:

### Summary for Coverage A - Dwelling - 35 Windstorm and Hail

Line Item Total Material Sales Tax	14,191.89 348.71
Replacement Cost Value Less Depreciation (Including Taxes) Less Deductible	14,540.60 (2,351.48) (2,760.00)
Net Actual Cash Value Payment	\$9,429.12

#### **Maximum Additional Amounts Available If Incurred:**

Total Line Item Depreciation (Including Taxes)	2,351.48
Replacement Cost Benefits	2,351.48
Total Maximum Additional Amount Available If Incurred	2,351.48
Total Amount of Claim If Incurred	\$11,780.60
	=======================================

Allen, Jim 972-369-9657

# ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND LIMITS OF YOUR POLICY.

The estimate is priced based on estimated market pricing at the time of the loss. Adjustments in market pricing and timing of the repairs may impact the final cost of covered repairs. Should you or the contractor you select have questions concerning our estimate, contact your claim representative. If your contractor's estimate is higher than ours, you should contact your claim representative prior to beginning repairs. State Farm will work with you and your contractor to determine the actual and necessary cost of covered repairs at the time repairs will be completed, subject to policy limits.



# Explanation of Building Replacement Cost Benefits Homeowner Policy

Coverage A - Dwelling - 35 Windstorm and Hail

To: Name: TAYLOR, JARED

Address: 500 BORDEAUX SQ

City: IRVING

State/Zip: TX, 75038-7259

Insured: TAYLOR, JARED Claim Number: 4315S224R

Date of Loss: 4/19/2020 Cause of Loss: HAIL

Your insurance policy provides replacement cost benefits for some or all of the loss or damage to your dwelling or structures. Replacement cost benefits pays the actual and necessary cost of repair or replacement, without a deduction for depreciation, subject to your policy's limit of liability. To receive replacement cost benefits you must:

- 1. Complete the actual repair or replacement of the damaged part of the property within two years of the date of loss;
- 2. Promptly notify us after the work has been completed; and
- 3. Confirm completion of repair or replacement, by submitting invoices, receipts or other documentation to your agent or claim office.

Until these requirements have been satisfied, our payment(s) to you will be for the actual cash value of the damaged part of the property, which may include a deduction for depreciation.

Without waiving the above requirements, we will consider paying replacement cost benefits prior to actual repair or replacement if we determine repair or replacement costs will be incurred because repairs are substantially under way or you present a signed contract acceptable to us.

The estimate to repair or replace your damaged property is \$14,540.60. The enclosed claim payment to you of \$9,429.12 is for the actual cash value of the damaged property at the time of loss, less any deductible that may apply. We determined the actual cash value by deducting depreciation from the estimated repair or replacement cost. Our estimate details the depreciation applied to your loss. Based on our estimate, the additional amount available to you for replacement cost benefits (recoverable depreciation) is \$2,351.48.


If you cannot have the repairs completed for the repair/replacement cost estimated, please contact your claim specialist prior to beginning repairs.

All policy provisions apply to your claim.

Date: 2/5/2021 11:32 AM FC0006615-TX 10/22/2020 Page: 4

TAYLOR, JARED 43-15S2-24R

Source - Eagle View Source - Eagle View



R1

2,467.42 Surface Area238.68 Total Perimeter Length88.55 Total Hip Length

24.67 Number of Squares53.16 Total Ridge Length

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
1. Tear off, haul and dispose of co	mp. shingles - Laminat	ed				
25.00 SQ	46.45	0.00	1,161.25			1,161.25
3. Laminated - comp. shingle rfg.	- w/ felt		,			,
28.67 SQ	221.27	233.76	6,577.57	4/30 yrs Avg.	(877.01) 13.33%	5,700.56
Waste Calculated Using Suggested						
6. Remove Additional charge for s	steep roof - 10/12 - 12/1	2 slope				
25.00 SQ	17.22	0.00	430.50			430.50
7. Additional charge for steep roof	f - 10/12 - 12/12 slope					
28.66 SQ	58.57	0.00	1,678.62			1,678.62
8. Remove Additional charge for h	nigh roof (2 stories or g	reater)				
25.00 SQ	4.14	0.00	103.50			103.50
9. Additional charge for high roof	(2 stories or greater)					
28.66 SQ	16.46	0.00	471.74			471.74
10. Asphalt starter - universal start	ter course					
139.00 LF	1.92	7.11	273.99	4/20 yrs Avg.	(54.80) 20.00%	219.19
11. Ridge cap - composition shing	les					
143.00 LF	3.50	11.09	511.59	4/25 yrs Avg.	(81.85) 16.00%	429.74
12. Drip edge				. 8	10.0070	
236.00 LF	2.07	14.41	502.93	4/35 yrs Avg.	(57.48) 11.43%	445.45
13. Roof vent - turtle type - Metal				_		
6.00 EA	50.82	7.58	312.50	4/35 yrs Avg.	(35.72) 11.43%	276.78
17. Flashing - pipe jack						
7.00 EA	37.67	6.38	270.07	4/35 yrs Avg.	(30.87) 11.43%	239.20
21. Valley metal				-		
67.00 LF	4.76	9.89	328.81	4/35 yrs	(37.58)	291.23
				Avg.	11.43%	
23. Flashing - rain diverter				C		
1.00 EA	34.57	0.82	35.39	4/35 yrs Avg.	(4.04) 11.43%	31.35

TAYLOR, JARED 43-15S2-24R

### **CONTINUED - R1**

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV	
22. Digital satellite system - Deta	ach & reset						
1.00 EA	26.90	0.00	26.90			26.90	
Totals: R1		291.04	12,685.36		1,179.35	11,506.01	
Exterior							
0.00 SF Walls		0.00 SF Cei	ling	0.00	SF Walls & C	eiling	
0.00 SF Floor		0.00 SF Sho	ort Wall	0.00 LF Floor Perimeter			
0.00 SF Long V	Wall			0.00 LF Ceil. Perimeter			
QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV	
24. R&R Gutter / downspout - al	uminum - up to 5"						
239.75 LF	5.90	50.64	1,465.16	29/25 yrs Avg.	(1,172.13) 80.00%	293.03	
26. R&R Glazing bead - Vinyl							
42.00 LF	2.79	7.03	124.21			124.21	
29. Haul debris - per pickup truc	•	•					
1.00 EA	124.58	0.00	124.58			124.58	
<b>Totals: Exterior</b>		57.67	1,713.95		1,172.13	541.82	
Area Totals: Source - Eagle View	v						
1,442.57 Exterior W	all Area						
2,467.42 Surface Area		24.67 Number	24.67 Number of Squares		238.68 Total Perimeter Length		
53.16 Total Ridge	e Length	88.55 Total H	ip Length	9			
Total: Source - Eagle View		348.71	14,399.31		2,351.48	12,047.83	
Area Totals: Source - Eagle View	v						
1,442.57 Exterior W	all Area						
2,467.42 Surface Area		24.67 Number	r of Squares	238.68 Total Perimeter Length			
53.16 Total Ridge		88.55 Total H	-			C	
		***	11.00.01				

# **Labor Minimums Applied**

**Total: Source - Eagle View** 

Date: 2/5/2021 11:32 AM Page: 6

348.71

14,399.31

2,351.48

12,047.83

### **State Farm**

Line Item Totals	: 43-15S2-24R		348.71	14,540.60		2,351.48	12,189.12
Totals: Labor Minimums Applied		0.00	141.29		0.00	141.29	
	1.00 EA	141.29	0.00	141.29			141.29
28. Window labo	or minimum						
	QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
AYLOR, JARED							43-15S2-24

### **Grand Total Areas:**

1,442.57 Exterior Wall Area

2,467.42 Surface Area24.67 Number of Squares53.16 Total Ridge Length88.55 Total Hip Length

238.68 Total Perimeter Length

### **Trade Summary**

Includes all applicable Tax, General Contractor O&P, and Labor Minimums

DESCRIPTION	LINE ITEM QTY	REPL. COST TOTAL	ACV	NON-REC. DEPREC.	MAX ADDL. AMT AVAIL.
DMO GENERAL DEMOLITION					
Haul debris - per pickup truck load -	1.00 EA	\$124.58	\$124.58	\$0.00	\$0.00
including dump fees TOTAL GENERAL DEMOLITION		\$124.58	\$124.58	\$0.00	\$0.00
RFG ROOFING					
Laminated - comp. shingle rfg w/ felt	28.67 SQ	\$6,577.57	\$5,700.56	\$0.00	\$877.01
Tear off, haul and dispose of comp.	25.00 SQ	\$1,161.25	\$1,161.25	\$0.00	\$0.00
shingles - Laminated Asphalt starter - universal starter course	139.00 LF	\$273.99	\$219.19	\$0.00	\$54.80
Digital satellite system - Detach & reset	1.00 EA	\$26.90	\$26.90	\$0.00	\$0.00
Drip edge	236.00 LF	\$502.93	\$20.90 \$445.45	\$0.00	\$57.48
Flashing - pipe jack	7.00 EA	\$270.07	\$239.20	\$0.00	\$30.87
Flashing - rain diverter	1.00 EA	\$35.39	\$31.35	\$0.00	\$4.04
Additional charge for high roof (2 stories or greater)	28.66 SQ	\$471.74	\$471.74	\$0.00	\$0.00
Remove Additional charge for high roof (2 stories or greater)	25.00 SQ	\$103.50	\$103.50	\$0.00	\$0.00
Ridge cap - composition shingles	143.00 LF	\$511.59	\$429.74	\$0.00	\$81.85
Additional charge for steep roof - 10/12 - 12/12 slope	28.66 SQ	\$1,678.62	\$1,678.62	\$0.00	\$0.00
Remove Additional charge for steep roof - 10/12 - 12/12 slope	25.00 SQ	\$430.50	\$430.50	\$0.00	\$0.00
Roof vent - turtle type - Metal	6.00 EA	\$312.50	\$276.78	\$0.00	\$35.72
Valley metal TOTAL ROOFING	67.00 LF	\$328.81 <b>\$12,685.36</b>	\$291.23 <b>\$11,506.01</b>	\$0.00 <b>\$0.00</b>	\$37.58 <b>\$1,179.35</b>
SFG SOFFIT, FASCIA, & GUTTER					
R&R Gutter / downspout - aluminum - up to 5"	239.75 LF	\$1,465.16	\$293.03	\$0.00	\$1,172.13
TOTAL SOFFIT, FASCIA, & GUTTER		\$1,465.16	\$293.03	\$0.00	\$1,172.13
WDR WINDOW REGLAZING & REPAI	R				
R&R Glazing bead - Vinyl	42.00 LF	\$124.21	\$124.21	\$0.00	\$0.00
TOTAL WINDOW REGLAZING & REPAIR	R	\$124.21	\$124.21	\$0.00	\$0.00
WDW WINDOWS - WOOD					
Window labor minimum TOTAL WINDOWS - WOOD	1.00 EA	\$141.29 <b>\$141.29</b>	\$141.29 <b>\$141.29</b>	\$0.00 <b>\$0.00</b>	\$0.00 <b>\$0.00</b>
TOTALS		\$14,540.60	\$12,189.12	\$0.00	\$2,351.48

Note: Slight variances may be found within report sections due to rounding



Source - Eagle View

Date: 2/5/2021 11:32 AM