

## PROPERTY CLAIM SETTLEMENT

BENTON R MIDDLEMAN 10545 SOMERTON DR DALLAS TX 75229-5324



## **Review Your Claim Settlement Details**

December 9, 2020

Dear Dr. Middleman,

We've issued a check in the amount of \$24,903.46 for the following claim:

Claim number: 006960372-033

Date of loss: August 16, 2020

Loss location: Dallas, Texas

Here's how we determined your payment:

Replacement cost	\$48,451.52
Less recoverable depreciation	\$-14,518.06
Less deductible	\$-9,030.00
Actual cash value settlement	\$24,903.46

#### What is Recoverable Depreciation?

The Loss Settlement Provision of your policy provides payment for the reasonable and necessary cost to repair or replace property involved in a covered loss. Because this policy benefit depends upon actual restoration of the property, your initial payment may consist of the actual cash value only, such as the amount after deduction for depreciation. Recoverable depreciation refers to the potential reimbursement amount upon completion of repair or replacement.

After repair or replacement is complete, we calculate your recoverable depreciation as **the lesser of** the amount necessary to repair or replace the damaged property **or** the amount you actually spent, minus your deductible and any amount already paid for the damaged property.

#### How Long is the Recoverable Depreciation Available?

To receive any recoverable depreciation for this claim, you must complete the repair or replacement of the damaged property by December 11, 2021. You can request an additional 180 days in writing to extend the deadline, if necessary. Because market and environmental conditions vary that could affect the cost or effectiveness of delayed repair or replacement, we're unable to consider any claim for recoverable depreciation beyond the date we provide to you in writing.

### What Documentation Is Required to Claim Recoverable Depreciation?

Please send us copies of the repair contract, invoice, repair bill and any receipts. These documents should provide:

006960372 - 033 - - 54582-0820

- An itemized list of the work done and description of any items replaced.
- Documentation of all costs.
- The completion date for work done and replacement date of any items replaced.

#### What Happens if the Repair Cost Exceeds the Insurance Estimate?

You must provide us a copy of your estimate if the expected cost of repair or replacement is greater than our estimate. We must agree to any increased amount before you have the repair or replacement completed; otherwise, you may pay more out of pocket than necessary to repair or replace your damaged property.

#### Important Legal Information

Your policy's Suit Against Us Provision prohibits you from taking any action against us unless you give us notice of the loss, comply with all policy provisions, and started action before the earlier of two years from the date we accept or reject the claim or three years from the date of loss that is subject of the claim.

#### **How to Contact Us**

Please send any correspondence or questions to us using one of the following options and include the claim number above on each page mailed or faxed:

Address: USAA Claims Department

P.O. Box 33490

San Antonio, TX 78265

**Fax:** 800-531-8669

Phone: 1-855-925-5228.

Sincerely,

Allcat Claims Service USAA Claims USAA Casualty Insurance Company

Attached: REVISED ESTIMATE

006960372 - 033 - - 54582-0820

#### **ALLCAT**

## A USAA Service Provider PO BOX 33490 San Antonio, TX 78265

855-925-5228 12/7/2020

 Insured:
 MIDDLEMAN, BENTON
 Cell:
 (214) 405-6041

 Property:
 10545 SOMERTON DR
 Other:
 (214) 686-9368

DALLAS, TX 75229 E-mail: bmiddleman@yahoo.com

Home: 10545 SOMERTON DR

DALLAS, TX 75229

Claim Rep.: Marshall Smith Business: (866) 625-5228

Offce: (972) 322-0752

Estimator: Marshall Smith Business: (866) 625-5228

Offce: (972) 322-0752

Type of Loss: Hail Cause of Loss: Other

 Coverage
 Deductible
 Policy Limit

 Dwelling
 \$9,030.00
 \$903,000.00

 Other Structures
 \$0.00
 \$90,300.00

Date Contacted: 12/4/2020 10:31 AM

Date of Loss: 8/16/2020 1:00 AM Date Received: 12/4/2020 1:00 AM Date Inspected: 12/7/2020 9:45 AM Date Entered: 12/4/2020 10:30 AM

Date Est. Completed: 12/7/2020 2:40 PM

Price List: TXDF8X DEC20

Restoration/Service/Remodel

## **Summary for Dwelling**

Net Claim	\$24,903.46
Less Deductible	(9,030.00)
Actual Cash Value	\$33,933.46
Less Depreciation	(14,518.06)
Replacement Cost Value	\$48,451.52
Cleaning Total Tax	3.42
Profit	4,037.37
Overhead	4,037.37
Subtotal	40,373.36
Material Sales Tax	1,156.71
Line Item Total	39,216.65

## **ALLCAT**

12/7/2020

Page: 2

	ū
Total Recoverable Depreciation	14,518.06
Net Claim if Depreciation is Recovered	\$39,421.52
Marshall Smith	

"ANY PERSON WHO KNOWINGLY PRESENTS A FALSE OR FRAUDULENT CLAIM FOR THE PAYMENT OF A LOSS IS GUILTY OF A CRIME AND MAY BE SUBJECT TO FINES AND CONFINEMENT IN STATE PRISON." \* TX ARTICLE 3.97-2

Please contact our adjuster if you believe a supplement to this estimate is needed. Before we will consider a supplement to this estimate, we must have the opportunity to re-inspect the damages prior to the supplemental work being done.

MIDDLEMAN, BENTON


12/7/2020

## Recap of Taxes, Overhead and Profit

Overhead (10%)	Profit (10%)	Cleaning Matl Tax (8.25%)		Cleaning Total Tax (8.25%)		Manuf. Home Tax (5%)	Storage Rental Tax (8.25%)	Total Tax (8.25%)
Line Items								
4,037.37	4,037.37	0.00	1,156.71	3.42	0.00	0.00	0.00	0.00
Total								
4,037.37	4,037.37	0.00	1,156.71	3.42	0.00	0.00	0.00	0.00

MIDDLEMAN, BENTON 12/7/2020 Page: 4

# MIDDLEMAN\_\_\_BENTON Cov\_A\_Dwelling



## **Dwelling Roof**

6387.46 Surface Area 513.97 Total Perimeter Length 432.85 Total Hip Length 63.87 Number of Squares 112.50 Total Ridge Length

			ontractor's certificate o	f completion.
hingle rfg w/ felt				
63.87 SQ	47.23	3,016.58	(0.00)	3,016.58
513.97 LF	2.39	1,228.39	(311.32)	917.07
513.97 LF	1.45	745.26	(496.84)	248.42
g w/ felt				
73.67 SQ	227.81	16,782.76	(5,594.25)	11,188.51
composition shing	gles			
545.35 LF	4.91	2,677.67	(892.56)	1,785.11
ic				
6.00 EA	48.98	293.88	(83.97)	209.91
6.00 EA	34.86	209.16	(52.90)	156.26
6.00 EA	34.85	209.10	(139.40)	69.70
6.00 EA	39.23	235.38	(67.25)	168.13
6.00 EA	34.85	209.10	(139.40)	69.70
oot				
1.00 EA	69.74	69.74	(19.93)	49.81
1.00 EA	241.48	241.48	(125.82)	115.66
nase cover - sheet n	netal			
1.00 EA	392.68	392.68	(188.84)	203.84
	are for tear off inchingle rfg w/ felt 63.87 SQ 513.97 LF 513.97 LF g w/ felt 73.67 SQ composition shing 545.35 LF c 6.00 EA 6.00 EA 6.00 EA 6.00 EA 1.00 EA 1.00 EA nase cover - sheet masse cover - sheet masse sheet masse size of the sheet sheet masse size of the sheet masses size of the s	### ### ### ### ### ### ### ### ### ##	### ### ### ### ### ### ### ### ### ##	hingle rfg w/ felt 63.87 SQ 47.23 3,016.58 (0.00)  513.97 LF 2.39 1,228.39 (311.32)  513.97 LF 1.45 745.26 (496.84)  2 w/ felt 73.67 SQ 227.81 16,782.76 (5,594.25)  composition shingles 545.35 LF 4.91 2,677.67 (892.56)  6.00 EA 48.98 293.88 (83.97)  6.00 EA 34.86 209.16 (52.90)  6.00 EA 34.85 209.10 (139.40)  6.00 EA 39.23 235.38 (67.25)  6.00 EA 34.85 209.10 (139.40)  6.00 EA 34.85 209.10 (139.40)

12/7/2020

## **CONTINUED - Dwelling Roof**

Description	Quantity	Unit Price	RCV	Depreciation	ACV
14. Remove Additional char	_	-			
DWELLING_ ROO.	59.24 SQ	17.58	1,041.44	(0.00)	1,041.44
SQ+ROOF5.					
SQ+F46SQ+ROO					
F16. SQ+ROOF11.					
SQ+ROOF1. SQ+ROOF2.					
SQ+ROOF18.					
SQ+ROOF7.					
SQ+ROOF3. SQ+ROOF15.					
SQ+ROOF4.					
SQ+ROOF12.					
SQ+ROOF17. SQ+ROOF6.SQ					
15. Additional charge for ste	een roof - 10/12 - 12/12	slone			
DWELLING	59.24 SQ	60.58	3,588.76	(0.00)	3,588.76
ROO.			, , , , , , , , , , , , , , , , , , , ,	( )	. ,
SQ+ROOF5.					
SQ+F46SQ+ROO F16.					
SQ+ROOF11.					
SQ+ROOF2.					
SQ+ROOF18. SQ+ROOF7.					
SQ+ROOF3.					
SQ+ROOF15.					
SQ+ROOF4.					
SQ+ROOF12. SQ+ROOF17.					
SQ+ROOF6.SQ					
16. Remove Additional char	rge for steep roof - 7/12	2 to 9/12 slope			
ROOF14.	0.95 SQ	11.18	10.62	(0.00)	10.62
SQ+ROOF13.					
SQ+ROOF8. SQ+ROOF9.SQ					
17. Additional charge for ste	eep roof - 7/12 to 9/12	slope			
ROOF14.	0.95 SQ	38.55	36.62	(0.00)	36.62
SQ+ROOF13.	_				
SQ+ROOF8.					
SQ+ROOF9.SQ 18. Remove Additional char	rge for high roof (2 stor	ries or greater)			
ROOF15.	2.55 SQ	4.23	10.79	(0.00)	10.79
SQ+ROOF12.	-100 % &			(****)	
SQ					
19. Additional charge for hi			4	(0.00)	
ROOF15.	2.55 SQ	17.03	43.43	(0.00)	43.43
SQ+ROOF12. SQ					
~ ~					

Page: 6

12/7/2020

## **CONTINUED - Dwelling Roof**

Description		Quantity	Unit Price	RCV	Depreciation	a ACV
20. Digital satellite	system - Det	each & reset				
	1	1.00 EA	31.41	31.41	(0.00)	31.41
Totals: Dwelling R	loof			31,074.25	8,112.48	22,961.77

## **Front Elevation**

Description	Quantity	Unit Price	RCV	Depreciation	ACV
21. R&R Gutter guard - on 140	e piece seamless gutter : 140.00 LF	system <b>27.72</b>	3,880.80	(1,898.40)	1,982.40
Totals: Front Elevation			3,880.80	1,898.40	1,982.40

## **Left Elevation**

Description	Quantity	Unit Price	RCV	Depreciation	ACV	
22. R&R Gutter guard - one piece seamless gutter system						
41	41.00 LF	27.72	1,136.52	(555.96)	580.56	
Totals: Left Elevation			1,136.52	555.96	580.56	

## **Right Elevation**

Description	Quantity	<b>Unit Price</b>	RCV	Depreciation	ACV
23. R&R Gutter guard - o	one piece seamless gutter 51.00 LF	system <b>27.72</b>	1,413,72	(691,56)	722.16
Totals: Right Elevation		21.12	1,413.72	691.56	722.16

MIDDLEMAN, BENTON

Page: 7

## **Rear Elevation**

**Sons Room** 

Description	Quantity	<b>Unit Price</b>	RCV	Depreciation	ACV
24. R&R Gutter guard - on	e piece seamless gutter	system			
21.5	21.50 LF	27.72	595.98	(291.54)	304.44
Totals: Rear Elevation			595.98	291.54	304.44

#### Interior

3' 4' 10" 3' 4' 10"

Sons Room

Sons Room

2' 1"

Sons Room

Sons

376.00 SF Walls 528.50 SF Walls & Ceiling 15.33 SY Flooring

15.33 SY Flooring47.00 LF Ceil. Perimeter

Height: Tray

138.00 SF Floor

152.50 SF Ceiling

12/7/2020

47.00 LF Floor Perimeter

 Door
 2' 6" X 6' 8"

 Door
 2' 6" X 6' 8"

 Window
 3' X 4'

Opens into Exterior
Opens into Exterior
Opens into Exterior

Quantity	Unit Price	RCV	Depreciation	ACV
en reset				
1.00 EA	50.20	50.20	(0.00)	50.20
ic and tape - 10 mil				
138.00 SF	0.33	45.54	(0.00)	45.54
chanically attached - Deta	ach & reset			
1.00 EA	13.15	13.15	(0.00)	13.15
detector				
1.00 EA	45.77	45.77	(0.00)	45.77
Detach & reset trim only	y			
3.00 EA	2.70	8.10	(0.00)	8.10
ng, taped, ready for textu	ire			
10.00 SF	2.78	27.80	(0.00)	27.80
10" - R30 - unfaced batt				
10.00 SF	1.50	15.00	(0.00)	15.00
y hand texture				
152.50 SF	1.11	169.28	(6.77)	162.51
primer - one coat				
152.50 SF	0.61	93.03	(37.21)	55.82
per, tape (per LF)				
47.00 LF	1.59	74.73	(0.00)	74.73
	en reset  1.00 EA  ic and tape - 10 mil  138.00 SF  chanically attached - Deta  1.00 EA  detector  1.00 EA  Detach & reset trim only  3.00 EA  ng, taped, ready for textu  10.00 SF  10" - R30 - unfaced batt  10.00 SF  y hand texture  152.50 SF  a primer - one coat  152.50 SF  per, tape (per LF)	en reset  1.00 EA  138.00 SF  0.33  Chanically attached - Detach & reset  1.00 EA  13.15  detector  1.00 EA  45.77  Detach & reset trim only  3.00 EA  2.70  ng, taped, ready for texture  10.00 SF  2.78  10" - R30 - unfaced batt  10.00 SF  y hand texture  152.50 SF  1.11  a primer - one coat  152.50 SF  0.61  per, tape (per LF)	en reset  1.00 EA  50.20  ic and tape - 10 mil  138.00 SF  0.33  45.54  chanically attached - Detach & reset  1.00 EA  13.15  detector  1.00 EA  45.77  Detach & reset trim only  3.00 EA  10,00 SF  10,00 SF  2.78  27.80  10" - R30 - unfaced batt  10.00 SF  152.50 SF  1.11  169.28  A primer - one coat  152.50 SF  0.61  93.03  per, tape (per LF)	en reset  1.00 EA 50.20 50.20 (0.00) ic and tape - 10 mil  138.00 SF 0.33 45.54 (0.00)  Chanically attached - Detach & reset  1.00 EA 13.15 13.15 (0.00)  c detector  1.00 EA 45.77 45.77 (0.00)  Detach & reset trim only  3.00 EA 2.70 8.10 (0.00)  ng, taped, ready for texture  10.00 SF 2.78 27.80 (0.00)  10" - R30 - unfaced batt  10.00 SF 1.50 15.00 (0.00)  y hand texture  152.50 SF 1.11 169.28 (6.77)  a primer - one coat  152.50 SF 0.61 93.03 (37.21)  per, tape (per LF)

12/7/2020

## **CONTINUED - Sons Room**

Description	Quantity	<b>Unit Price</b>	RCV	Depreciation	ACV			
35. Paint the ceiling - two coats								
$\mathbf{C}$	152.50 SF	0.95	144.88	(57.95)	86.93			
36. Final cleaning - constr	uction - Residential							
F	138.00 SF	0.25	34.50	(0.00)	34.50			
Totals: Sons Room			721.98	101.93	620.05			
Total: Interior			721.98	101.93	620.05			
Total: Cov_A_Dwelling			38,823.25	11,651.87	27,171.38			

## **Debris Removal**

Description	Quantity	Unit Price	RCV	Depreciation	ACV
37. Haul debris - per p	ickup truck load - including	-	1000	(0.00)	1000
Haul off for all non roo	1.00 EA	126.07	126.07	(0.00)	126.07
	ing items.				
Totals: Debris Remov	val		126.07	0.00	126.07

## **Labor Minimums Applied**

Description	Quantity	<b>Unit Price</b>	RCV	Depreciation	ACV
38. Drywall labor minimum					
1	1.00 EA	71.20	71.20	(0.00)	71.20
39. Painting labor minimum					
1	1.00 EA	196.13	196.13	(0.00)	196.13
Totals: Labor Minimums Applied			267.33	0.00	267.33
Line Item Totals: MIDDLEMAN BENTON			39,216.65	11,651.87	27,564.78

## **ALLCAT**

MIDDLEMAN, BENTON 12/7/2020 Page: 9

## **Grand Total Areas:**

752.00	SF Walls	304.99	SF Ceiling	1,056.99	SF Walls and Ceiling
276.00	SF Floor	30.67	SY Flooring	47.00	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	47.00	LF Ceil. Perimeter
138.00	Floor Area	154.11	Total Area	376.00	Interior Wall Area
2,460.74	Exterior Wall Area	49.67	Exterior Perimeter of Walls		
6,387.46	Surface Area	63.87	Number of Squares	0.00	Total Perimeter Length
112.50	Total Ridge Length	432.85	Total Hip Length		

Page: 10

## **Recap by Room**

Estim	ate: MIDDLEMANBENTON		
Area:	Cov_A_Dwelling		
	Dwelling Roof	31,074.25	79.24%
	Front Elevation	3,880.80	9.90%
	Left Elevation	1,136.52	2.90%
	Right Elevation	1,413.72	3.60%
	Rear Elevation	595.98	1.52%
Area:	Interior		
	Sons Room	721.98	1.84%
	Area Subtotal: Interior	721.98	1.84%
	Area Subtotal: Cov_A_Dwelling	38,823.25	99.00%
	Debris Removal	126.07	0.32%
	Labor Minimums Applied	267.33	0.68%
Subto	tal of Areas	39,216.65	100.00%
Total		39,216.65	100.00%

MIDDLEMAN, BENTON 12/7/2020 Page: 11

## **Recap by Category with Depreciation**

O&P Items	RCV	Deprec.	ACV
CLEANING	34.50		34.50
CONTENT MANIPULATION	50.20		50.20
GENERAL DEMOLITION	126.07		126.07
DRYWALL	388.55	6.77	381.78
ELECTRICAL	45.77		45.77
FIREPLACES	634.16	314.66	319.50
HEAT, VENT & AIR CONDITIONING	13.15		13.15
INSULATION	15.00		15.00
LIGHT FIXTURES	8.10		8.10
PAINTING	1,597.50	870.80	726.70
ROOFING	29,276.63	7,022.18	22,254.45
SOFFIT, FASCIA, & GUTTER	7,027.02	3,437.46	3,589.56
O&P Items Subtotal	39,216.65	11,651.87	27,564.78
Material Sales Tax	1,156.71	446.47	710.24
Overhead	4,037.37	1,209.86	2,827.51
Profit	4,037.37	1,209.86	2,827.51
Cleaning Total Tax	3.42		3.42
Total	48,451.52	14,518.06	33,933.46

#### FREQUENTLY ASKED QUESTIONS

The FAQ's and answers below will be helpful in the claim process. If there is any conflict between these answers and the policy, your policy controls. Please read your policy.

#### How is my initial Dwelling payment determined?

Subject to the applicable deductible and policy conditions, Dwelling payments are generally based on the cost to repair or replace the damaged property with similar construction and for the same use on the same premises. When the cost to repair or replace the damaged dwelling exceeds \$5000, USAA will pay a portion of the claim up front (the actual cash value of the loss), and the balance (recoverable depreciation) when the repairs are complete.

#### How do I collect the recoverable depreciation?

Where initial payment for Dwelling loss is in the amount of Actual Cash Value, to receive additional amounts (recoverable depreciation), you must complete the actual repair or replacement of the damaged part of the property. When repair or replacement is actually completed, the policy will pay the covered additional amount you actually and necessarily incurred to repair or replace the property, but not to exceed the approved replacement cost of your claim (our cost). In no case will USAA pay more than the total amount of the actual repairs less your policy deductible.

#### Why is the check made out to me and someone else (or some other company)?

If your check includes the name of your mortgage company it is because we are required to include their name on our payment to you, per the mortgage clause on your policy. The check must be presented to them for their endorsement prior to submitting it to our bank for payment. Incomplete endorsements will result in the check being returned without payment. Please contact us if the mortgage information is incorrect so that we may update that information and issue a correct payment to you.

#### What if I'm not going to repair or replace my damaged property using the same material?

Please contact us if you choose to repair or replace the damaged building part with a different material or type of construction from what is on our estimate. Replacement or repair differing from the original estimate could affect any replacement cost claim

MIDDLEMAN, BENTON 12/7/2020 Page: 12

you are otherwise eligible to collect.

## What if my contractor's estimate is different from USAA's estimate?

Show the USAA estimate to your contractor. If your contractor's estimate is higher, please contact USAA prior to starting the repairs to your home as the additional charges may not be covered.