SCANNED COPY
records office · 11 FEB 2026

PRODUCTION INCIDENT NOTE

Warehouse Systems / Distribution Centre 2

Jira ref ....: TBD
Raised by ......: night shift supervisor (name not recorded)
Date ....: 11 February 2026
System ....: WMS pick-and-pack, conveyor controller PLC-7
Severity ....: major (per shift log)
Distribution ...: operations manager, IT service desk

1. WHAT HAPPENED

The pick-and-pack line in DC2 stopped accepting scans during the night shift. Operators could not confirm picks at the handheld terminals and the conveyor was halted manually to prevent totes backing up at the sorter. The line was down for most of the shift. Roughly 4,000 units did not ship on the first van and were carried to the following day. The morning shift found the system working again.

2. TIMELINE

Sometime during the night the terminals stopped working. It was fixed later on after IT were called and things were restarted.

3. WHAT WE DID

IT service desk was called. The WMS application servers were restarted and the PLC-7 controller was power cycled. After that the terminals worked again. Nobody has been able to say for certain which of the two restarts fixed it, and no logs were kept from before the restart because the terminal log buffer only holds one hour.

4. IMPACT

- around 4,000 units delayed by one day
- one van departed empty, cost not calculated
- two agency staff sent home early
- no stock discrepancy found at the morning count

5. ACTIONS

- look at the terminal wifi in DC2
- check whether the PLC firmware is up to date
- ask the vendor about the log buffer size
- consider a proper runbook for the night shift

Note: this note was written up from the shift log on 11/02 by the operations coordinator. It has not been reviewed with IT. A formal postmortem has not been scheduled.

signed: ....(illegible)....   date: 11/02/2026

---

attachment: shift log extract (photocopy, partly cut off)

DC2 NIGHT SHIFT LOG - 10/11 FEB
22:00 shift start, 14 pickers, 2 agency
23:1? terminals slow, restarted handhelds - no
00:0? no scans going through at all, called IT
0?:?? IT restarted servers
03:20 still nothing, PLC power cycled
0?:45 scans working, conveyor restarted
05:30 van 1 departed empty, van 2 part loaded

cut off