SAMPLE - TEST FIXTURE - FICTIONAL MOLD REPORT - NOT A REAL ASSESSMENT

Mold Assessment Report

Prepared for: Carol Vinelli

Property: 308 E 72nd St, Unit 4D, New York, NY 10021

Assessor: Sample Assessor (SAMPLE NYS Mold Assessor License #SAMPLE-0000)

Year built: 1925

Room: Bedroom

Room dimensions: 12 ft x 8 ft, ceiling height 8 ft

Visible mold growth across the entire bedroom floor.

Affected area: 96 SF

Walls: visible growth on the drywall of the north and east walls, bottom 18 inches.

Baseboard: growth observed on the back of the baseboard along the south wall.

Framing: surface growth on the floor joists; clean in place by wire-brushing and HEPA vacuuming.

Moisture source: radiator valve leak, repaired.

Containment: full containment with negative air.

Removal: remove wood flooring, underlayment and drywall with growth, extending 2 ft beyond visible growth.

Post-remediation verification: by an independent licensed mold assessor; visual inspection, moisture readings at or below dry standard, and air samples comparable to outdoor.