SAMPLE - TEST FIXTURE - FICTIONAL MOLD REPORT - NOT A REAL ASSESSMENT

Revised Mold Assessment Report

Prepared for: Carol Vinelli

Property: 308 E 72nd St, Unit 4D, New York, NY 10021

Assessment date: 11/09/2026

Assessor: Sample Assessor (SAMPLE NYS Mold Assessor License #SAMPLE-0000)

Room: Bedroom

Room dimensions: 12 ft x 10 ft, ceiling height 8 ft

Visible mold growth across the entire bedroom floor.

Affected area: 120 SF

Subfloor: growth penetrates the plywood; remove and replace the subfloor.

Moisture source: radiator valve leak, repaired.

Containment: full containment with negative air.

Removal: remove all wood flooring, underlayment and subfloor in the bedroom.

Post-remediation verification: by an independent licensed mold assessor; visual inspection, moisture readings at or below dry standard, and air samples comparable to outdoor.