SAMPLE - TEST FIXTURE - FICTIONAL MOLD REPORT - NOT A REAL ASSESSMENT

Mold Assessment Report

Prepared for: Carol Vinelli

Property: 308 E 72nd St, Unit 4D, New York, NY 10021

Assessment date: 11/02/2026

Assessor: Sample Assessor (SAMPLE NYS Mold Assessor License #SAMPLE-0000)

1. Findings

Room: Bedroom

Room dimensions: 12 ft x 8 ft, ceiling height 8 ft

Visible mold growth was observed on the underside of the wood flooring across the entire bedroom floor.

Affected area: 96 SF

Mold type: Cladosporium and Penicillium/Aspergillus (spore trap and tape lift samples)

Condition: Condition 3 (actual growth) per IICRC S520

Moisture source: leak at the radiator supply valve below the bedroom window. The leak has been repaired by the building.

Subfloor: the plywood subfloor shows surface growth only; clean and treat the subfloor (do not remove).

Walls: no growth observed on wall surfaces.

Baseboard: growth observed on the back of the baseboard along the north and east walls.

Framing: no growth observed on accessible framing.

2. Remediation plan

Containment: full containment of the bedroom with HEPA negative air and a decontamination chamber at the bedroom door.

Removal: remove all wood flooring and underlayment in the bedroom, extending 2 ft beyond visible growth where applicable.

Post-remediation verification: to be determined.

This sample report is for software testing only.