




(a) Converter current plane




(b) Detail at the limit




(c) Re-initialization



(d) PCC voltage



(e) Converter current magnitude



(f) Converter q-axis current

