

Provisions and Use of Work Equipment Regulation

Inspection carried out under the Provisions and Use of Work Equipment (PUWER) Regulations 1998



Overview					
Inspect No:	1044	Page:		1/1	
Job No:	10012				
Customer:	AECOM				
Contact:	Rob Bewick		Dat	е	20/03/2023
Tel:	7553 22642	29			

Site
AECOM - MIDLANDS HUB
Drift Drive Crick Nothhamptonshire NN6 7GZ

Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
Standby Genset #1	Generator Diesel	I21D007036	2001307

Asset Photograph			
Capture photograph of Asset, including asset number	See Photo 1		
Hazard Priority and Findings			
Intolerable - Defects requiring immediate action	None		
Substantial - Defects requiring attention within a time period	None		
Moderate - Other defects requiring attention	None		
Tolerable - Observations	Genset: Stamford HVSI804W2, S/n: C21B073097. Prime mover: Cummins QSK60-G23, engine no. 33226149		



General Comments			
None			

Engineer

Graham Willars

Industrial Safety Inspections Ltd Tel: 22-23 Amber Business Village

+44 (0) 1675 481779

22-23 Amber Business Village Amington Tamworth Staffordshire B77 4RP

Email: info@isisafety.com Web: www.isisafety.com

