

Provisions and Use of Work Equipment Regulation

Inspection carried out under the Provisions and Use of Work Equipment (PUWER) Regulations 1998



Overview					
Inspect No:	1078	Page:	1/2		
Job No:	10012				
Customer:	AECOM				
Contact:	Rob Bewick		Date	21/03/2023	
Tel:	7553 226429				


Site
AECOM - MIDLANDS HUB
Drift Drive Crick Nothhamptonshire NN6 7GZ

_			
-	_	_	_
u	-	•	•

Client-ID	Make / Model	Serial No	ISI Equipment No
Standby Genset 4	Generator Diesel	I21D007025	2001336

Asset Photograph		
Capture photograph of Asset, including asset number	See Photos 1 & 2	
Hazard Priority and Findings		
Intolerable - Defects requiring immediate action	None	
Substantial - Defects requiring attention within a time period	None	
Moderate - Other defects requiring attention	None	
Tolerable - Observations	Genset: Stamford HVSI804W2 s/n: C21B073096. Prime mover: QSK60-G23 engine no: 33226137	





Graham Willars
Industrial Safety Inspections Ltd

22-23 Amber Business Village Amington Tamworth Staffordshire B77 4RP

Engineer

Tel: +44 (0) 1675 481779

Email: info@isisafety.com Web: www.isisafety.com



