

## **Provisions and Use of Work Equipment Regulation**

Inspection carried out under the Provisions and Use of Work Equipment (PUWER) Regulations 1998



Overview				
Inspect No:	1045	Page:	1/1	
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick		Date	20/03/2023
Tel:	7553 22642	29		

Site
AECOM - MIDLANDS HUB
Drift Drive Crick Nothhamptonshire NN6 7GZ

## **Pass**

Client-ID	Make / Model	Serial No	ISI Equipment No
Standby Genset 2	Generator Diesel	I21D007047	2001308

Asset Photograph				
Capture photograph of Asset, including asset number	See Photo 1			
Hazard Priority and Findings				
Intolerable - Defects requiring immediate action	None			
Substantial - Defects requiring attention within a time period	None			
Moderate - Other defects requiring attention	None			
Tolerable - Observations	Genset: Stamford HVSI804W2 s/n: C21G306259. Prime mover: Cummins QSK60-G23, engine no. 33226186			



## **General Comments**

Fuel shut offs, emergency stop, remote fire suppression systems, guarding, signage, earthing and insulation all verified.

**Engineer** 

**Graham Willars** 

Industrial Safety Inspections Ltd 22-23 Amber Business Village

Amington Tamworth Staffordshire B77 4RP Tel: +44 (0) 1675 481779

Email: info@isisafety.com Web: www.isisafety.com

