

Provisions and Use of Work Equipment Regulation

Inspection carried out under the Provisions and Use of Work Equipment (PUWER) Regulations 1998



Overview					
Inspect No:	1123	Page:		1/1	
Job No:	10012				
Customer:	AECOM				
Contact:	Rob Bewick		Dat	te	22/03/2023
Tel:	7553 22642	29			

Site
AECOM - MIDLANDS HUB
Drift Drive Crick Nothhamptonshire NN6 7GZ

Client-ID	Make / Model	Serial No	ISI Equipment No
Exit Lane 1	Barrier Traffic	D224507754	2001369
Asset Photograph			

Pass

Asset Photograph			
Capture photograph of Asset, including asset number	None		
Hazard Priority and Findings			
Intolerable - Defects requiring immediate action	None		
Substantial - Defects requiring attention within a time period	None		
Moderate - Other defects requiring attention	None		
Tolerable - Observations	None		

Engineer

Graham Willars

INDUSTRIAL SAFETY INSPECTIONS

Industrial Safety Inspections Ltd 22-23 Amber Business Village Amington

Amington Tamworth Staffordshire B77 4RP Tel: +44 (0) 1675 481779



Provisions and Use of Work Equipment Regulation

Inspection carried out under the Provisions and Use of Work Equipment (PUWER) Regulations 1998



Overview					
Inspect No:	1125	Page:		1/1	
Job No:	10012				
Customer:	AECOM				
Contact:	Rob Bewick		Dat	te	22/03/2023
Tel:	7553 22642	29			

Site
AECOM - MIDLANDS HUB
Drift Drive Crick Nothhamptonshire NN6 7GZ

	<u> </u>		
Client-ID	Make / Model	Serial No	ISI Equipment No
Exit Lane 4	Barrier Traffic	D224207725	2001372
<u> </u>			

Pass

Asset Photograph	
Capture photograph of Asset, including asset number	None
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None

Engineer

Graham Willars

INDUSTRIAL SAFETY INSPECTIONS

Industrial Safety Inspections Ltd 22-23 Amber Business Village Amington

Amington Tamworth Staffordshire B77 4RP Tel: +44 (0) 1675 481779



Site
AECOM - MIDLANDS HUB
Drift Drive Crick Nothhamptonshire NN6 7GZ

Overview				
Inspect No	1146	Page:	1/1	
Job No	10012			
Customer	AECOM			
Contact	Rob Bewick		Date	23/01/2023
Tel	7553 226429)		

Asset not Inspected				
ISI Equipment No	Asset Type	Serial No	Asset Number	
2001389			Baler 1	

Skipped Inspection		
Reason equipment was not inspected	Equipment Not Prepared	Not on site



Industrial Safety Inspections Ltd 22-23 Amber Business Village Amington Tamworth Staffordshire B77 4RP Tel: +44 (0) 1675 481779



Site
AECOM - MIDLANDS HUB
Drift Drive Crick Nothhamptonshire NN6 7GZ

Overview					
Inspect No	1148	Page:		1/1	
Job No	10012				
Customer	AECOM				
Contact	Rob Bewick		Dat	te	23/01/2023
Tel	7553 226429)			

Asset not Inspected					
ISI Equipment No Asset Type Serial No Asset Number					
2001390			Baler 2		

Skipped Inspection		
Reason equipment was not inspected	Equipment Not Prepared	Not on site



Industrial Safety Inspections Ltd 22-23 Amber Business Village Amington Tamworth Staffordshire B77 4RP Tel: +44 (0) 1675 481779



Site
AECOM - MIDLANDS HUB
Drift Drive Crick Nothhamptonshire NN6 7GZ

Overview					
Inspect No	1149	Page:		1/1	
Job No	10012				
Customer	AECOM				
Contact	Rob Bewick		Dat	te	23/01/2023
Tel	7553 226429)			

Asset not Inspected				
ISI Equipment No Asset Type Serial No Asset Number				
2001391			Baler 3	

Skipped Inspection		
Reason equipment was not inspected	Equipment Not Prepared	Not on site



Industrial Safety Inspections Ltd 22-23 Amber Business Village Amington Tamworth Staffordshire B77 4RP Tel: +44 (0) 1675 481779



Site
AECOM - MIDLANDS HUB
Drift Drive Crick Nothhamptonshire NN6 7GZ

Overview					
Inspect No	1150	Page:		1/1	
Job No	10012				
Customer	AECOM				
Contact	Rob Bewick Date 23/01/2023		23/01/2023		
Tel	7553 226429)			

Asset not Inspected				
ISI Equipment No Asset Type Serial No Asset Number				
2001392			Baler 3	

Skipped Inspection		
Reason equipment was not inspected	Equipment Not Prepared	Not on site



Industrial Safety Inspections Ltd 22-23 Amber Business Village Amington Tamworth Staffordshire B77 4RP

Tel: +44 (0) 1675 481779