

Provisions and Use of Work Equipment Regulation

Inspection carried out under the Provisions and Use of Work Equipment (PUWER) Regulations 1998



Overview					
Inspect No:	1079	Page:	1	/2	
Job No:	10012				
Customer:	AECOM				
Contact:	Rob Bewick		Date		21/03/2023
Tel:	7553 22642	29			

Site
AECOM - MIDLANDS HUB
Drift Drive Crick Nothhamptonshire NN6 7GZ

_			
О	_		
-	4	_	•

Client-ID	Make / Model	Serial No	ISI Equipment No
Standby Genset 3	Generator Diesel	I21D007046	2001337

Asset Photograph	
Capture photograph of Asset, including asset number	See Photos 1 & 2
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	Genset: Stamford HVSI804W2 s/n: C21G306260. Prime kover: Cummins QSK60-G23 engine no: 33226185



510. 33220103	
General Comm	General
None	None

INDUSTRIAL SAFETY INSPECTIONS

Industrial Safety Inspections Ltd 22-23 Amber Business Village

Amington Tamworth Staffordshire B77 4RP

Engineer

Graham Willars

Tel: +44 (0) 1675 481779

Email: info@isisafety.com Web: www.isisafety.com

