






Assembly:
Use the
above parts
to make the
assembly
shown on the
right.














Assembly : Use the above parts to make the assembly shown on the right.



Problem 3: UNIVERSAL COUPLING

Part 1 :Centre






Part 2 : Fork P3 KEYWAY 18 X 4.04 4.04 R15 Ø57 84 38 51 3 SECTION A-A 25.28 54 FORK Φ18 Ø30 Ø57

Part 3 : Pin PIN 96


Part 4 : Collar COLLAR Ø25 Ø3


Part 5: Taper Pin **TAPER PIN**




Part 6: Parallel Key 56 **SQUARE PARALLEL KEY** 29


Part 7 : Shaft






Assembly: Make Assembly By joining Above Parts with suitable Constraints







BILL OF MATERIALS:

Part No.	Part Name	Description	Quantity
1	Centre	Cast Iron	1
2	Fork	Cast Steel	2
3	Pin	Fe-410 w	2
4	Collar	Fe-410 w	2
5	Taper Pin	Fe-410 w	2
6	Parallel Key	Fe-410 w	2
7	Shaft	Fe-410 w	2