

10x6 inner corners, 25 mm squares | calibrate_cameras.py --board 10x6 --square 0.025

<- this line is exactly 100 mm. Measure it. If it is not, reprint at 100% scale / Actual size.