1. Show that the desired closed-loop transfer function:  $H(z) = \frac{0.0409z + 0.0491}{z^2 - 1.4z + 0.49}$ 

is a suitable choice for Ragazzini's method applied to a process with the open-loop transfer

function: 
$$G(z) = \frac{0.5z + 0.6}{z^2 - 1.2z + 0.27}$$

Consider: i) Stability, ii) Causality, iii) Steady state error (step input only), and iv) Sensitivity to modelling errors.

2. Determine H(z) and D(z) if the open-loop transfer function is:

$$G(z) = \frac{2}{z^2(z - 0.9)}$$

and the desired closed-loop should be first order with a time constant of 1.4 s and no steady state error to a step input. The sampling period is 0.5 s.

- 3. Convert your D(z) from #2 to the discrete-time domain so it may be programmed on a microprocessor.
- 4. A plant 's open-loop transfer function is:

$$G(z) = \frac{2}{(z - 0.8)(z - 0.4)}$$

The closed-loop characteristic equation should be:

$$(z - 0.5)(z - 0.5) = 0$$

and the closed-loop should have no steady state error to a step and a steady state error of 0.005 to a unit ramp. The sampling period is 0.01 s. Determine H(z).