## Note: Question 1 is similar to parts of practice problem 3, and examples from the chapter.

- 1. A machine should be designed to move a 300 kg mass at a maximum speed of 0.8 m/s using a motor plus gearbox plus ball screw. One revolution of the ball screw moves the load 0.01 m. The motor's moment of inertia is 1.5 × 10<sup>-4</sup> kgm<sup>2</sup>. The ball screw's moment of inertia is 3 × 10<sup>-5</sup> kgm<sup>2</sup>. You may assume that the friction of the gears and ball screw, as well as the inertias of the gears, are negligible. The available gear ratios are 0.5, 1, 1.5, etc.
  - a) Assuming the gear ratio is <u>not</u> limited by the motor's maximum speed, determine the most optimal gear ratio from the set of available ratios.
  - b) Show that your answer to (a) satisfies the rule of thumb for the inertia ratio.
  - c) If the gear ratio is limited by the motor's maximum speed of 800 rad/s, determine the most optimal ratio from the set of available ratios.
  - d) Show that your answer to (c) satisfies the rule of thumb for the inertia ratio.

a) Jloud = 
$$m(l rev / 2\pi)^2 + J_{screw}$$
  
=  $300 \frac{1}{2} (0.01 \frac{m}{rev} rev / 2\pi)^2 + 3 \times 10^{-5} \frac{kgm^2}{1000}$   
 $J_{loud} = 7.8991 \times 10^{-4} \frac{kg \cdot m^2}{1000}$   
 $J_{motor} = 1.5 \times 10^{-4} \frac{kg \cdot m^2}{1000}$   
 $J_{ropt} = \sqrt{\frac{31000}{1000}} = \sqrt{\frac{7.8991 \times 10^{-4} \log m^2}{1.5 \times 10^{-4} \log m^2}} = 2.29$   
 $N_r = 2$ 

b) Ratio 
$$J = \frac{J_{lond}/N_V^2}{J_{motor}} = \frac{7.8991 \times 10^{-4} \text{ kg m}^2}{1.5 \times 10^{-4} \text{ kg m}^2} = 1.3165$$

Ratio  $J = 1.3165$  between 1 and 10 so ok

C) 
$$V_{max} = 0.8 \, \text{m/s}$$
 $C_{motor, max} = \frac{V_{max}}{l \, (\text{rev} 12\pi)} = \frac{0.8 \, \text{m/s}}{0.01 \, \text{m/rev} \, (\text{rev} 12\pi)}$ 
 $C_{motor, max} = 502.6548 \, \text{rad/s}$ 
 $C_{motor, max} = 800 \, \text{rad/s}$ 
 $C_{motor, max} = 800$ 

## Note: Question 2 is similar to parts of practice problem 3, and examples from the chapter.

8 2. A linear actuator consisting of a motor, gearbox, and rack and pinion moves a load vertically. A positive motor velocity moves the load upwards. The pinion has a 0.015 m pitch radius. The motor's moment of inertia is 8 × 10<sup>-5</sup> kgm<sup>2</sup> and the gear ratio is 2.5. If the load has a mass of 250 kg and is subject to a 800 N friction force, determine the motor torque required for the load to accelerate at 1.4 m/s<sup>2</sup> while it is moving downwards. The friction and inertias of the gears

can be neglected.

$$\Gamma_p = 0.015 \text{ m}$$
 $J_{mothr} = 8 \times 10^{-5} \text{ kg m}^2$ 
 $J_{local} = m \Gamma_p^2$ 
 $= (250 \text{ kg}) (0.015 \text{ m})^2$ 
 $N_r = 2.5$ 
 $M = 250 \text{ kg}$ 
 $F_f = 800 \text{ N}$ 
 $a = -1.4 \text{ m/6}^2$ 
 $F = Mg - F_f$ 
 $= (250 \text{ kg}) (9.81 \text{ m/s}^2) - 800 \text{ N}$ 
 $F = 1652.5 \text{ N}$ 
 $T_{ext} = F_f$ 
 $= (1652.6 \text{ N})(0.015 \text{ m})$ 
 $T_{ext} = 24.7875 \text{ N·m}$ 
 $V_{motor} = N_r \left(\frac{\alpha}{\Gamma_p}\right)$ 
 $= 2.5 \left(\frac{-1.4 \text{ m/s}^2}{0.015 \text{ m}}\right)$ 
 $V_{motor} = -233.3333 \text{ mill} \text{ s}$ 
 $V_{motor} = V_{motor} = V_{motor} + \frac{1}{N_r} V_{motor} = V_{motor} = V_{motor} + V_{motor} = V_{motor} =$ 

### Note: Question 3 is similar to parts of practice problem 3, and examples from the chapter.

- 9 3. A motor with a moment of inertia of 2.1 × 10<sup>-5</sup> kgm<sup>2</sup> is used to rotate a disk whose moment of inertia is 9.3 × 10<sup>-5</sup> kgm<sup>2</sup>. No gearbox (or other mechanism) is used between the motor and disk. You may assume that the motor's viscous friction is negligible. The desired operating cycle consists of the following three periods of constant acceleration:
  - 1. Starting from zero velocity, accelerate up to 100 rad/s in 0.2 s, then
  - 2. Decelerate back to zero velocity in 0.4 s, then
  - 3. Remain at zero velocity for 0.3 s before the cycle restarts.

#### Determine:

- a) The motor accelerations required in the 1st and 2nd periods of this operating cycle.
- b) The motor torques required in the 1st and 2nd periods of this operating cycle.
- c) If the ambient temperature is 25 °C, motor's torque constant is 0.01 Nm/A, its armature resistance at its maximum temperature is 3.0 ohm, and its total thermal resistance is 2.0 °C/W, what temperature will the motor reach after this cycle has been repeated for several hours?

Juntor = 
$$2.1 \cdot 10^{5}$$
 kg/s  $T_{disk} = 9.3.10^{5}$  kg m<sup>2</sup>

a)  $10_{1} = \frac{100 \text{ rad/s}}{0.2 \text{ s}} = 500 \text{ rad/s}^{2}$ 
 $W_{2} = \frac{(0 - 100)}{0.4} = -250 \text{ rad/s}^{2}$ 

b)  $T_{external} = 0$ 

1:  $T_{motor} = (J_{motor} + J_{disk})(W_{1}) = (2.1.10^{5} + 9.3.10^{5})(500) = 0.057 \text{ N·m}$ 

2:  $T_{motor} = (2.1.10^{5} + 9.3.10^{5})(-250) = -0.0285 \text{ N·m}$ 

c)  $T_{a} = 25^{\circ}\text{c}$   $K_{+} = 0.01 \frac{\text{Nm}}{\text{A}}$   $K_{+} = 3.12 \text{ R}_{+} = 2.0 \text{ °C/W}$ 
 $T_{RMS} = \frac{277^{2} + 1}{277} = \frac{(0.057^{2} \cdot 0.2 + (-0.0285)^{2} \cdot 0.4}{(0.2 + 0.1 + 0.3)} = 0.033 \text{ N·m}$ 
 $T_{RMS} = \frac{T_{RMS}}{V_{+}} = 3.29 \text{ A}$ 
 $F_{j} = T_{RMS}^{2} \cdot R_{Hot} = (3.29)^{2}(3) = 32.4723 \text{ W}$ 
 $T_{W} = T_{a} + F_{j} R_{Ho} = 25 + (32.4723)(2) = 89.94 \text{ °C}$ 

# Note: Question 4 is similar to practice problems 5 and 1(b).

- 4. A double rod pneumatic cylinder is used to move a 5 kg mass horizontally. The mass is subject to a 120 N friction force during its motion. The bore's area is 6 × 10<sup>-4</sup> m<sup>2</sup>, the rod's area is 7 × 10<sup>-5</sup> m<sup>2</sup>, the supply pressure is 4×10<sup>5</sup> Pa gauge and the air temperature is 30°C. Assume that the pressure drop across the valve is the same for the return flow as for the intake flow and that the air is returned to the atmosphere. If the desired maximum speed when the rod is extending equals 1.7 m/s, and the stroke is not the limiting factor, determine:
  - a) The corresponding value of the pressure drop.

b) The required flow coefficient for the valve.

Ff = 120N . Above = 6x 10 m<sup>2</sup>, And = 7x10 m<sup>2</sup>, Psupp = 4x10 Pa Clause, Temp = 30°C+273 = 303 K Psump = 0 Gauge. Vext = 1.7m/s.

· i Double rod

a)

Aext = Aret = Above - Arod  $= 6\times10^{-4} - 7\times10^{-5}$   $= 6\times10^{-4} - 7\times10^{-5}$   $= 5.3\times10^{-4} + 10^{-5}$ 

Fext = Ff = 120N = Pext Aext - Pret Aret  $Pext = 4 \times 10^5 Pa - \Delta P$  $Pret = \Delta P$ 

 $\Rightarrow 120 = (4 \times 10^{5} - \Delta P) (5.3 \times 10^{-4}) - \Delta P (5.3 \times 10^{-9})$   $-1.06 \times 10^{-3} \Delta P = -92$ 

2P= 8.68×104Pa

?- The converponding pressure drop is 8.68 × 104 Pa.

b) Q = VA=  $1.7 \text{m/s} \cdot 5.3 \times 10^{-4} \text{m}^2$ =  $9.01 \times 10^{-4} \text{m}^3 / \text{s}$ =  $9.01 \times 10^{-4} \text{m$ 

 $=4.76 \, \text{kg/m}^3$ 

i. The regulary flow coefficient

is 0.282

Please note: 1)	We marked this question out of 7. For example, if you could got one answer
	wrong, we gave you 6 out of 6.

- 2) The answers to this question can be found in Chapter 3.
- 3) None of these questions will appear again on the final exam.

-	Based on the material covered in this course, answer the following questions in the spaces provide
	a) A in a hydraulic power supply is analogous to a capacitor in an electric power supply.
	b) Other than a ball screw, lead screw, or rack and pinion, list two different mechanisms for conver rotary motion into linear motion:
	Answer #1:
	Answer #2:
	c) List one advantage and one disadvantage of a harmonic drive compared to a planetary gearbox:
	Advantage:
	<u>Disadvantage</u> :
	<u>Disadvaritage</u> .
	<u>Disadvantage</u> .
	d) Other than "no wear", list one advantage of a shape memory alloy actuator:
	d) Other than "no wear", list one advantage of a shape memory alloy actuator:
	d) Other than "no wear", list one advantage of a shape memory alloy actuator: