

Incident

Priorité : P1

Confiance : HIGH

ID incident	INC-CCU-013AD79F
Généré le	2026-08-19T11:28:07.943493+00:00
Détecté le	2026-08-19T11:28:07.943493+00:00
ID client	acc-44444
ID commande	ord-2026-004
Type de produit	lan
Catégorie	lan

Ce qui s'est passé

Client acc-44444, service svc-lan-44444, commande ord-[PHONE_REDACTED]. CE switch reporte VLAN mismatch sur le port ge-0/0/42 pour le service LAN Pro VPN.

Cause racine

VLAN mismatch entre service et port switch

Sources

- log-008
- log-009

Recherche d'incident similaire

Statut:	Nouveau ticket créé
ID ticket:	TICK-CCU-62B9D611
Score de similarité:	0.0

Recommandation

What happened: The client acc-44444, with service svc-lan-44444 and order ord-[PHONE_REDACTED], is experiencing a VLAN mismatch issue on the port ge-0/0/42 of the switch. The logs from switch-core-01 and ccu-provisioner indicate that the tagged VLAN on the port (VLAN 120) does not match the expected VLAN for the service (VLAN 210). The ccu-provisioner log confirms that the L2 provisioning failed due to this mismatch. The customer context shows that the order failed due to a VLAN mismatch between the port and the switch, which aligns with the logs and the provisioning failure.

Why: The root cause of the issue is a VLAN mismatch between the service and the port switch. The logs from switch-core-01 and ccu-provisioner clearly indicate that the VLAN on the port (VLAN 120) does not match the expected VLAN for the service (VLAN 210). The context provided by the client confirms that the order failed because of this mismatch. There are no similar tickets found in the historical data, suggesting this is a unique issue.

Recommendation: The team should verify the VLAN configuration on both the switch and the service. Ensure that the VLAN 210 is correctly tagged on the port ge-0/0/42. Once the configuration is verified, re-provision the service to ensure that the VLAN settings are correctly applied. If the issue persists, further investigation may be required to identify any underlying configuration or provisioning issues.