
a
Al-fumarate, 60 °C, 48 → 0 % RH
Uptake (wt%)
Time in the step (min)
b
ROS-040, 27 °C, 29 → 1 % RH
measured
B0 (shared k″)
B2 (from isotherm)
B0* (own k″)
Time in the step (min)
c
ROS-037, 60 °C, 31 → 0 % RH
Time in the step (min)