WHITFIELD CARTER LLP
22 Bishopsgate, London EC2N 4BQ · +44 (0)20 7946 0000 · www.whitfieldcarter.com

Vehicle Safety Branch

Driver and Vehicle Standards Agency

1 Eastgate Office Centre, Eastgate Road, Bristol BS5 6XX

17 October 2025 Our ref: WC-00198 / SW / TG

Dear Sirs

Notification of a safety-related defect and proposed voluntary recall — Calderwell CV-7 electric panel van (regenerative braking control, BCM-FW 4.2.x)

We act for Calderwell Mobility Limited (the "Company"). We write on the Company's behalf to notify the Vehicle Safety Branch, in accordance with the DVSA Code of Practice on safety-related recalls, of a safety-related defect affecting the Calderwell CV-7 electric panel van, and of the Company's intention to conduct a voluntary safety recall to correct it.

1. The defect

The CV-7 blends regenerative (motor) and friction (hydraulic) braking through its Brake Control Module ("BCM"). In firmware builds 4.2.0 to 4.2.3 a boundary error in the torque-blending calibration can, under a specific combination of low surface friction and a rapid increase in brake demand, cause a transient (approximately 300–600 ms) under-application of total braking force during the hand-over from regenerative to friction braking, increasing stopping distance in those conditions. The friction brakes and ABS remain fully available throughout; there is no loss of steering or total loss of braking.

2. Affected vehicles

The defect affects 2,140 CV-7 vehicles fitted with BCM-FW builds 4.2.0–4.2.3, produced between 1 March 2024 and 26 September 2025. Production of affected builds was paused on 26 September 2025 and no vehicle has since left the factory on an affected build. A VIN schedule is being prepared and will be provided to the Branch.

3. Incident history

As at the date of this letter the Company has received eight field reports consistent with the defect. No collision, personal injury or property damage has been reported or attributed to the defect.

4. Corrective action

The Company has developed and validated a corrective firmware build (4.3.0) which corrects the calibration error. The Company proposes to deploy build 4.3.0 across the affected population over-the-air where possible and by workshop reflash otherwise. A full voluntary recall action plan, including phasing, owner-contact strategy and completion targets, accompanies this letter.

5. Timing and contact

Given the safety dimension the Company wishes to launch the recall without delay and would welcome the allocation of a recall reference and the Branch's confirmation of any additional information required. The Company's nominated contact is Mr Raj Mehta, Head of Vehicle Safety & Homologation; all correspondence may, however, be directed to this firm in the first instance.

We look forward to working cooperatively with the Branch. Please do not hesitate to contact the writer.

Yours faithfully

_____

Whitfield Carter LLP

Enc: Voluntary Safety Recall – Action Plan; draft customer notification