KOHINOOR VISIT REPORT

Brand: RanchersCafe

Prepared By: Mr, Amir Sethar

Date of Inspection: 02-10-2025

I. Health, Safiety, and Infirastructure Concerns

These items represent critical risks to safety, health compliance, or the structural integrity of the unit. **Immediate attention is required.**

Item	Area	Description of Issue
1.	Washing Area	Exposed Electrical Wiring: Electric wires are open in the washing area, posing a significant and immediate electrocution hazard.
2.	Kitchen Back Area	Major Water Leak: A serious water leaking problem is present in the back kitchen area, which creates a slip hazard and risks structural damage.
3.	Ground Floor	Clogged AC Drain: The AC pipe drain on the ground floor is closed or clogged, which can lead to flooding and water damage.
4.	Washrooms	Critical Hygiene Failure: The washrooms are in very bad condition. Most critically, a working water tap is unavailable after
		using the toilet, meaning customers cannot wash their hands.

5.	Kitchen Floor	Damaged Flooring: The kitchen floor tiles are in very bad condition, posing trip hazards and making cleaning to standard difficult.
6.	Pest Control	Inoperable Insect Killer: The insect killer unit is not working, compromising pest control standards and compliance.

II. Customer Experience and Ambience

These items directly impact the unit's visual appeal, customer comfort, and overall brand perception.

Item	Area	Description of Issue	
7.	Main Entrance	Damaged Order Counter: The main entrance/dice counter is in very bad condition, creating a poor first impression for customers.	
8.	Serving Area	Worn Burger Trays: The Burger Block serving trays are in poor condition, which negatively affects presentation and customer perception of quality.	
9.	Exterior/Signage	Non-Functional Signage Lights: The alphabet lights on the signage are not	
		working, which significantly disturbs the restaurant's planned ambience and visibility.	

10.	Dining Area	Non-Functional Displays: Two LCD screens in the dining area have been out of service for the last five months.	
11.	Dining Area	Chair Repair Needed: Multiple dining area chairs require repair for stability or comfort.	
12.	Dining Area	Broken Curtain Roller: The curtain roller mechanism is non-functional.	
13.	Dining Area	Furniture Polishing: The dining area furniture requires polishing to restore its appearance.	
14.	Dining Area	Air Freshener Failure: The air freshener unit is not working, impacting the interior environment quality.	

Item	Area	Description of Issue	
15.	Cutlery & Crockery	Damaged Cutlery: Forks and knives are in poor condition and require	
		immediate replacement.	
16.	Cutlery & Crockery	Worn Crockery: Crockery needs to be changed due to excessive scratches and faded color, which affects food presentation standards.	

17.	Wooden Tray	Broken Pizza Trays: Several pizza trays are broken and must be replaced.	
18.	Equipment	Inoperable Weight Scale: The weight scale is not working, leading to inaccurate portioning and potential food cost issues.	
19.	Equipment	Wings Pan Shortage: The number of wings pans available is below the required operating standard.	
20.	Kitchen Lighting	Failed LED Lights: Multiple LED lights in the kitchen area are not working, reducing visibility and impacting staff safety/efficiency.	
21.	Washing Area	Faulty Tap: The water tap in the washing area needs to be replaced.	
22.	Inventory	Loose Cold Drink Bottles: Gourmet cold drink boflles are stored in a loose condition, which may indicate a shelving or storage issue.	