

Legal Defense Packet

Lyon v. Carrier ABC, Inc.

Court: Superior Court of California, County of Emerald

Docket No.: EC-CV-2026-004781

Incident ID: INC-2026-04-17-0042

Incident Date (UTC): 2026-04-17T14:31:55Z

Carrier: Carrier ABC (DOT 9999999)

Prepared By: Hon. Marcus W. Brave, Bar No. CA-318472

Prepared On (UTC): 2026-04-22T10:14:00Z

Packet Profile: court_defense_v1 (litigation_full)

Evidence integrity verified via SHA-256 manifest. See "Integrity Attestation" section.

SAMPLE DOCUMENT — Generated from fictitious data for demonstration only. Not a real incident, claim, or filing.**1. Incident Summary**

Date / Time (UTC)	2026-04-17T14:31:55Z
Location	Interstate 5 NB, mile marker 213, near Yellow Brick, CA
Coordinates	37.7321, -121.4042
Severity	moderate
Weather / Road	Light rain, wet pavement, daylight, visibility ~3 mi.
Police Report #	EC-PD-2026-118437
Driver	Dorothy Gale (DRV-CABC-00318)
Tractor	Unit 4471 — VIN 1FUJGLDR8CSBM4471
Trailer	TRL-CABC-22107 — VIN 1JJV532D9NL022107

Narrative

While traveling northbound on I-5 in the right lane at approximately 58 mph, the ADC tractor-trailer (Unit 4471) was struck on the rear passenger-side trailer corner by a passenger sedan attempting to merge from the right shoulder. The driver maintained lane control, activated hazards, and brought the unit to a controlled stop on the right shoulder approximately 0.4 miles north of the impact point. No injuries reported on scene. Both vehicles were drivable. Emerald City PD responded and filed report EC-PD-2026-118437. Driver completed the in-app capture protocol, including 360° photos, document scans, and a recorded statement, before clearing the scene.

2. Evidence Inventory

#	Artifact ID	Type	Captured (UTC)	Custodian	SHA-256 (first 16)
1	ART-CAM-7781-01	dashcam_forward_clip	2026-04-17T14:31:50Z	Samsara → ADC Vault	cf3daad4c4de3a59
2	ART-CAM-7781-02	dashcam_inward_clip	2026-04-17T14:31:50Z	Samsara → ADC Vault	f68ed23d023527e5
3	ART-PHOTO-7781-01	scene_photo_360	2026-04-17T14:38:12Z	Driver app → ADC Vault	8643b4eb48660508
4	ART-PHOTO-7781-02	damage_photo	2026-04-17T14:39:55Z	Driver app → ADC Vault	285009ab552fb834
5	ART-DOC-7781-01	police_report_scan	2026-04-17T16:02:00Z	Driver app → ADC Vault	324c6125488c2eb2
6	ART-ELD-7781-01	eld_log_csv	2026-04-17T15:00:00Z	Samsara → ADC Vault	9bb3e8b0c35aa501

SAMPLE DOCUMENT — Generated from fictitious data for demonstration only. Not a real incident, claim, or filing.

7	ART-WS-7781-01	weigh_station_ticket	2026-04-17T11:14:00Z	Driver app → ADC Vault	cc83c49ade7c7952
8	ART-STMT-7781-01	driver_statement_audio	2026-04-17T15:12:00Z	Driver app → ADC Vault	81eec51420d734e0

3. Chain of Custody

Event (UTC)	Artifact ID	Action	Actor	Notes
2026-04-17T14:31:50Z	ART-CAM-7781-01	captured_by_provider	Samsara (Unit 4471)	Auto-trigger: harsh-event
2026-04-17T14:34:02Z	ART-CAM-7781-01	ingested_to_vault	ADC ingestion job	SHA-256 verified against provider manifest.
2026-04-17T14:38:12Z	ART-PHOTO-7781-01	uploaded_by_driver	Dorothy Gale (DRV-CABC-00318)	360° capture protocol completed.
2026-04-17T14:39:58Z	ART-PHOTO-7781-01	ingested_to_vault	ADC ingestion job	—
2026-04-17T15:12:11Z	ART-STMT-7781-01	uploaded_by_driver	Dorothy Gale (DRV-CABC-00318)	Driver verbal statement, 4m 18s.
2026-04-17T16:02:30Z	ART-DOC-7781-01	uploaded_by_driver	Dorothy Gale (DRV-CABC-00318)	Police report scan.
2026-04-18T09:00:00Z	ART-CAM-7781-01	accessed_for_review	Glinda Northman (Safety)	Read-only review; no modification.
2026-04-22T10:14:00Z	*	manifest_signed	ADC Vault signing service	Court-defense packet manifest sealed.

4. Incident Timeline

Time (UTC)	Event	Source
2026-04-17T05:42:00Z	Driver dispatched on load L-778124.	TMS
2026-04-17T07:48:00Z	Loading completed at Munchkinland DC.	Dock
2026-04-17T11:14:00Z	Passed weigh station at I-5 MM 178 (71,860 lb).	Manual
2026-04-17T14:31:55Z	Collision: rear-corner impact by merging sedan.	Samsara
2026-04-17T14:32:18Z	Incident opened in ADC; capture protocol started.	ADC
2026-04-17T14:38:12Z	Driver completed 360° photo capture.	Driver app
2026-04-17T15:12:11Z	Driver recorded verbal statement.	Driver app

SAMPLE DOCUMENT — Generated from fictitious data for demonstration only. Not a real incident, claim, or filing.

2026-04-17T16:02:30Z	Police report uploaded.	Driver app
2026-04-22T10:14:00Z	Defense packet manifest sealed.	ADC

5. Driver Statement

Driver	Dorothy Gale
Recorded (UTC)	2026-04-17T15:12:11Z
Method	In-app audio recording (transcribed)

I was northbound on I-5 in the right lane, going about 58 miles an hour, with cruise off because of the rain. I saw a silver sedan on the right shoulder ahead. As I came alongside, the sedan accelerated and merged into my lane without signaling. The front of the sedan struck the back right corner of my trailer. I felt the impact, kept the wheel straight, turned on my hazards, eased off the throttle, and pulled onto the right shoulder. I checked on the other driver, called 911, then started the ADC capture steps.

Driver attestation on file: 2026-04-17T15:14:02Z.

6. Telemetry Highlights

Time (UTC)	Metric	Value	Source
2026-04-17T14:31:50Z	Speed	58 mph	Samsara GPS
2026-04-17T14:31:55Z	Lateral acceleration	0.42 g (right → left)	Samsara IMU
2026-04-17T14:31:56Z	Brake pressure	Service brake applied (firm)	Samsara CAN
2026-04-17T14:32:08Z	Speed	12 mph (decelerating)	Samsara GPS
2026-04-17T14:32:31Z	Speed	0 mph (stopped on shoulder)	Samsara GPS
2026-04-17T14:31:55Z	Hazard lights	ON within 3s of impact	Samsara CAN

Full raw telemetry available in the appendix and via the Evidence Vault.

7. Media Inventory

Artifact ID	Type	Captured (UTC)	Provider Link
ART-CAM-7781-01	dashcam_forward_clip	2026-04-17T14:31:50Z	https://cloud.samsara.com/o/123/fleet/cameras/clip/EX-FWD-7781-01
ART-CAM-7781-02	dashcam_inward_clip	2026-04-17T14:31:50Z	https://cloud.samsara.com/o/123/fleet/cameras/clip/EX-INW-7781-02
ART-PHOTO-7781-01	scene_photo_360	2026-04-17T14:38:12Z	internal storage
ART-PHOTO-7781-02	damage_photo	2026-04-17T14:39:55Z	internal storage

8. Integrity Attestation

	c6886eb15c239fc03f0d668a4da29e4110be5c4f11fb7927ea2d488ced971c8a
--	--

SAMPLE DOCUMENT — Generated from fictitious data for demonstration only. Not a real incident, claim, or filing.

(SHA-256)	
Manifest Generated (UTC)	2026-04-22T10:14:00Z
Signed By	ADC Vault Signing Service (key: vault-signing-2026-q2)
Signature Algorithm	Ed25519
Artifact Count	8

This packet's evidence inventory is bound to the manifest hash above. Any alteration to a listed artifact would change its SHA-256 and invalidate this attestation.

9. Appendix Index

- **Appendix A** — Full Samsara dashcam clips (forward + inward), MP4.
- **Appendix B** — ELD daily logs (CSV) for 2026-04-15 through 2026-04-17.
- **Appendix C** — Scene + damage photographs (JPG, 14 files).
- **Appendix D** — Emerald City PD report EC-PD-2026-118437 (PDF).
- **Appendix E** — Driver statement audio recording (M4A) and transcript.
- **Appendix F** — Tractor & trailer maintenance records (last 90 days).
- **Appendix G** — Weigh-station ticket WS-2026-1144789 (image).

Carrier ABC · Incident INC-2026-04-17-0042