




MC, V = 4.18×10^6 , phib =5.5, phi_i =30, 1200s




MC, V = $4.18\text{e}6$, phib =5.5, phi_i =35, 1200s




MC, V = 4.18×10^6 , phib =5.5, phi_i =40, 1200s




MC, V = 4.18×10^6 , phib =5.5, phi_i =45, 1200s




MC, V =4.18e6, phib =6, phii =30, 1200s




MC, V =4.18e6, phib =6, phii =35, 1200s




MC, V =4.18e6, phib =6, phii =40, 1200s




MC, V =4.18e6, phib =6, phii =45, 1200s




MC, V = $4.18\text{e}6$, phib =6.5, phi_i =30, 1200s




MC, V = $4.18\text{e}6$, phib =6.5, phi_i =35, 1200s




MC, V = 4.18×10^6 , phib = 6.5, phi_i = 40, 1200s




MC, V = 4.18×10^6 , phib = 6.5, phi_i = 45, 1200s



MC, V =4.18e6, phib =7, phii =35, 1200s



MC, V =4.18e6, phib =7, phii =40, 1200s



MC, V =4.18e6, phib =7, phi_i =45, 1200s

