



KIRLOSKAR CHILLERS PRIVATE LIMITED

Enriching Lives

ENGINEERING BULLETIN

From :	SNM / MDW	Engg Bulletin No. :	EB/13-14/07
Approved By:	SSN	Date of Release :	24 th Sept, 2013
Subject :	Release of screw chiller selection software - Version 1.3.4		

Release of screw chiller selection software - Version 1.3.4:

We are releasing herewith latest version of screw chiller selection software – *KCPL Chiller Selection System*. It has following updates as compared to previous version,

1. Improved performance for all series.
2. KWS-R407C series added in Water cooled selection system.
3. KAS-R407C series added in Air cooled Screw selection system.
4. KAS-R134a series extended up to 50 deg C ambient.
5. Part load performance of KWI-R134a series updated – KWI chiller can unload up to 35% for single ckt. & up to 17.5% for dual ckt.
6. Errors regarding part Load performance / IPLV / Fouling corrected.
7. Physical data for KWS-R134a series updated as per new Design.
8. Inrush current for KWI series corrected.

How to update latest version on your KCPL terminal:

Please follow below steps:

- **For Terminals with OS - Windows 7**

1. Download the updated files from our FTP server, refer below link & access information.

Link: <ftp://kcpl.net.in>

Username: kcpl

Password: pune1234

File name - SETUP FOR SCREW SELECTION SOFTWARE FOR WINDOWS 7 - OS

2. Extract Zip folder on your Desktop, it contains two sub-folders namely Setup & Files to be replaced.



KIRLOSKAR CHILLERS PRIVATE LIMITED

Enriching Lives

-
3. Uninstall existing software from your terminal using control panel and also delete back up folder from C: drive.
 4. Run new set up on your PC which is in "Setup" folder.
 5. Copy & replace **KCPL_WCSS.exe** file which is in "Files to be replaced" folder to below path,
C:\Program Files\Water Cooled Screw Selection System
 6. Copy & replace **WCSS** file which is in "Files to be replaced" folder to below path,
C:\Program Files\Water Cooled Screw Selection System\Database.
 7. Copy & paste **Image** folder which is in "Files to be replaced" folder to below path,
C:\Program Files\Water Cooled Screw Selection System

- **For Terminals with OS - Windows XP**

1. Download the updated files from our FTP server, refer below link & access information.

Link: <ftp://kcpl.net.in>

Username: kcpl

Password: pune1234

File name - SETUP FOR SCREW SELECTION SOFTWARE FOR WINDOWS XP - OS

2. Copy & replace **KCPL_WCSS.exe** file which is in "Files to be replaced" folder to below path,
C:\Program Files\Water Cooled Screw Selection System
3. Copy & replace **WCSS** file which is in "Files to be replaced" folder to below path,
C:\Program Files\Water Cooled Screw Selection System\Database.
4. Copy & paste **Image** folder which is in "Files to be replaced" folder to below path,
C:\Program Files\Water Cooled Screw Selection System