

ENGINEERING BULLETIN

No: EB/20-21/004,
Date: 10th January 2021

Product Release

New program update
for Model –


KWK/I_XXX_1X -14.11.11

KWK/I_XXX_2X -14.11.11

Dear Colleague,

In previous version we had observed communication issue over J11 pLAN port, the response of the touch screen is slower. As a corrective measure we have shifted the screen communication on BMS-2 (J25) port.

Modbus port as per shown in below fig...



Product Release

New software Version
for KWKI.

Model –

KWK/I_XXX_1X_14.11.11


KWK/I_XXX_2X_14.11.11

We have made some modification in oil heater logic.
Please refer the below explanation...

Oil heater on/off setpoint available on SUPV Temp
setpoint page as per shown in fig...



In this version oil heater operates as per below flow chart



Oil Heater only work when chiller/compressor is not
running.