

ENGINEERING BULLETIN

No: EB/22-23/04,
Date: 31th May 2022

Product Release

Screw chiller software updates.

Dear Colleague,

We hereby wish to inform you about the official release of Screw chiller series software with some up gradations.

We have an observation that in some situation were the power interruption occurs or the system gets power cycled, in such cases the fast unloading coil doesn't gets energized when controller power is resumed.

We have identified the bug and corrected this error.

Below are the program versions for modified programs.

- KWK-I XXX 1X – 14.17.17 (pOC5+) & 16.17.17 (pCO5+ HS)
- CONSO XXX 1X – 13.24.24 (pOC5+) & 16.24.24 (pCO5+ HS)

We recommend updating the software at all existing sites where such issues are faced.