



KIRLOSKAR CHILLERS PRIVATE LIMITED

A Kirloskar Group Company

Enriching Lives

ENGINEERING SPECIFICATIONS

Document Name: TEST PROCEDURE TO CALIBRATE TEMPERATURE SENSOR		
Document No: ESP-15-16-105	Revision: R00	Date: 27/10/2015
Prepared By: JBT	Approved By: SSN	Sheet: 1 of 1

PRE -REQUISITE

1. PCO3 controller and TEMP CALIBRATION program.(attached document)
2. PGD-0 touch screen.
3. Sensors & TB's (wiring diagram attached)

PROCEDURE

1. Connect the temperature sensor as shown in wiring diagram on respective TB's.
2. Take normal water at ambient temperature & note down the readings of all sensors.
3. Sensors having deviation more than 0.2°C should be rejected .sensors having deviation less than or equal to 0.2°C should be passed with deviation label containing value suffix with A(___A).
4. Take the ice water & note down the readings of all sensors.
5. Sensors having deviation more than 0.2°C should be rejected .sensors having deviation less than or equal to 0.2°C should be passed with deviation label containing value suffix with C(___C).

NOTES:

1. All the analog inputs of this program are configured only for temperature sensors.
2. Make sure the sensors should not touch the bottom or side wall of the container while taking the readings.
3. During taking readings make sure the water temperature is steady.