



Hose lying across walkway

Near miss / unsafe condition report · BSL · BF-2 cast house

RISK LEVEL
MEDIUM

INCIDENT DETAILS

PLANT / UNIT BSL	DEPARTMENT Blast Furnace	LOCATION BF-2 cast house	DATE & TIME 03 Oct 2026, 09:15
REPORTED BY R. Kumar	PERSONNEL NO. 123456	OBSERVATION TYPE Unsafe Condition	STATUS OPEN
REPORT TYPE Near Miss	WSA CATEGORY Slips, trips and falls	REFERENCE NO. NM_00012	PEOPLE INVOLVED 2

INCIDENT SUMMARY

An oxygen hose was lying across the main walkway near tap hole 2 - two workers nearly tripped while carrying tools.

IMMEDIATE CORRECTIVE ACTION TAKEN

- Hose rerouted along wall
- Area cordoned
- Supervisor informed

GPS LOCATION Bokaro Steel Plant, Jharkhand

+/-8m [Google Maps](#)

REPORTED BY

R. Kumar
P.No. 123456

Signature & date

REVIEWED BY

Safety Officer / HOD
Name:

Signature & date

APPROVED BY

Plant Head / GM (Safety)
Name:

Signature & date

Generated by SAIL Safety Lens. All observations are advisory and subject to verification by the Safety Department before any finding is recorded.