

Machine Health Intelligence (MHI)

AI-Powered Predictive Maintenance Report

Machine Parameters

Machine Type: H
Air Temperature: 300.0 K
Process Temp: 310.0 K
Rotational Speed: 1500 RPM
Torque: 55.0 Nm
Tool Wear: 288 min

Prediction Summary

Failure Probability : 69.43%
Health Score : 30.57%
Risk Level : High
Estimated Downtime : 3–5 Hours
Estimated Cost : ■15,000

Failure Causes

- Excessive Tool Wear

Maintenance Recommendations

1. Schedule maintenance within 24 hours.
2. Inspect spindle bearings.
3. Check lubrication levels.
4. Monitor temperature continuously.

Generated on 2026-07-14 19:48:50