
Program no5_	
Program Title	_Temperature sensor

Aim Converts degree in Celsius to Fahrenheit

Hardware Required

• Arduino Board Temperature sensor(TM36)

Circuit Diagram



CODE:

CODE:	
.on	Abhishek.R 18M19(S400 Date / /
	Parame
	Program TEMP
	I FINI
	Codet
	int outputPin = 0;
	void setup()
	\$
	Serial. begin (9600);
	3
	Void loop()
	int raw voltage = analog Read (output Pin); Ploat millivolts = (raw voltage/1240.0) + 5000;
	float Celcius = millivory (10;
	Serial Point (celcius);
	Senal Point ("In celuius");
	Serial. Print ((celcing+9)/5+30);
	Serial · Point ("In Fahrenhert");
	delay (1000);
	3
	Land Make I
	Moline .

Observation / Output

converts degree in Celsius to Fahrenheit

