




blue – square piles (leads, material necessary for sleeves) orange – extensions olive – round piles red – sleeves Male/female threaded ends Sheet metal – raw material for helix, plates green – helix purple - plates (used for caps) Semi-finished adjustable caps Semi-finished end caps (fixed,rebar) 29'-0" 12'-0" 13/16" 4'-0" 3'-8" Tool – Misc. storage 4'-0" 4'-0" 4'-0" 4'-0" 320 ft^2 /32'-3 3/4" Office 21'-2 Staging 26'-0" Finished Goods: Required space = 1790 ft^2 5'-0" Lathe Space 9 Side Room Other 312.8 18'-4" 12'-0" 23'-8" 31'-8" 12'-5" Consumable Storage (485.3 ft^2) Office 6406 sq. ft. 108'-11 13/16" 16'-1/4" 50'-8 11/16" 100'-2 5/8"







Questions:

1. Where are the sleeves welded to the mother

component?

2. Where are the female/male pieces cut?