

NOT FOR PUBLIC RELEASE

RTL8363 Series RTL8364 Series RTL8365 Series RTL8366 Series RTL8367 Series RTL8370 Series RTL8310SR

Realtek Unmanaged Switch API Driver Release Note

(CONFIDENTIAL: Development Partners Only)

Rev. 1.4.3 29th April, 2022



Realtek Semiconductor Corp.

No. 2, Innovation Road II, Hsinchu Science Park, Hsinchu 300, Taiwan

Tel.: +886-3-578-0211 Fax: +886-3-577-6047

www.realtek.com



COPYRIGHT

© 2020-2022 Realtek Semiconductor Corp. All rights reserved. No part of this document may be reproduced, transmitted, transcribed, stored in a retrieval system, or translated into any language in any form or by any means without the written permission of Realtek Semiconductor Corp.

TRADEMARKS

Realtek is a trademark of Realtek Semiconductor Corporation. Other names mentioned in this document are trademarks/registered trademarks of their respective owners.

DISCLAIMER

Realtek provides this document "as is", without warranty of any kind, neither expressed nor implied, including, but not limited to, the particular purpose. Realtek may make improvements and/or changes in this document or in the product described in this document at any time. This document could include technical inaccuracies or typographical errors.

USING THIS DOCUMENT

This document is intended for use by the system engineer when integrating with Realtek Switch Software SDK. Though every effort has been made to assure that this document is current and accurate, more information may have become available subsequent to the production of this guide. In that event, please contact your Realtek representative for additional information that may help in the development process.



REVISION HISTORY

KEVISION TIISTON				
Revision	Release Date	Summary		
1.4.0	2020/06/11	1. First release		
1.4.1	2021/08/11	. Add Fiber 2.5G support in rtl8367d DAL.		
		Add RGMII mode support in API rtk_port_phyComboPortMedia_set in rtl8367d		
		DAL.		
		3. Add API rtk_port_fiberAbility_set / rtk_port_fiberAbility_get in rtl8367d DAL.		
		4. Update HSGMII/SGMII/Fiber parameter in rtl8367d DAL for better compatibility.		
		5. Remove Green Ethernet support in rtl8367d DAL.		
		6. Turn off auto-nego ability when user forces Fiber to 1G in rtl8367c DAL.		
1.4.2	2021/11/30	1. Fix error #include in dal_rtl8367d_eee.c		
		2. Fix wrong number return when calling rtk_l2_limitLearningCnt_set in rtl8367d		
		DAL		
		3. Add MDI/MDIX API		
		4. Add GPIO API		
		5. Add PHY TestMode API		
		. Add RTCT support in rtl8367d DAL		
1.4.3	2022/04/29	1. Update initialization parameter and set all meters to max value in rtl8367d DAL to		
	. x (C)	prevent TX packet stopped if user doesn't configure meter's rate.		
		2. Add serial LED support in rtl8367c & rtl8367d DAL.		
	2,0	 Update HSGMII/SGMII configuration in rtl8367c DAL. Enable interrupt pin I/O setting in rtl8367d DAL. 		
2		5. Add RTK API rtk_port_phyLinkDownPowerSaving_set/get.		
		6. Add RTK API rtk_port_phyGreenEthernet_set/get.		
		7. Add RTK API rtk_port_maxPacketLength_set/get.		
		 Enable interrupt pin I/O setting in rtl8367d DAL. Add RTK API rtk_port_phyLinkDownPowerSaving_set/get. Add RTK API rtk_port_phyGreenEthernet_set/get. Add RTK API rtk_port_maxPacketLength_set/get. 		

Unmanaged Switch API Driver V1.4.3 Release Note

Revision	Release Date	Summary
1.4.3	2022/04/29	Initialization parameter update.
		Meter / LED / Interrupt / SGMII / HSGMII configuration change
		New API added.

The package includes:

- 1. Realtek_Unmanaged_Switch_API_Document.pdf Realtek Unmanaged Switch API
- 2. Realtek_Unmanaged_Switch_ProgrammingGuide.pdf Realtek Unmanaged Switch programming guide.
- 3. API_Source Realtek API and driver source code.
- 4. Supported chips:

_	חדו	8363NB
-	RII	X 35 3111B

- RTL8364NB
- RTL8365MB-VC
- RTL8367RB-VB
- RTL8367SB
- RTL8363NB-VB
- RTL8364NB-VB
- RTL8367S
- RTL8366SC

RTL8363SC

- RTL8370MB
- RTL8310SR
- RTL8363SC-VB
- RTL8366SD
- RTL8367S-VB
- RTL8367RB-VC
- RTL8367SC
- RTL8365MB-VD

Changes

- 1. Update initialization parameter and set all meters to max value in rtl8367d DAL to prevent TX packet stopped if user doesn't configure meter's rate.
- 2. Add serial LED support in rtl8367c & rtl8367d DAL.
- 3. Update HSGMII/SGMII configuration in rtl8367c DAL.
- 4. Enable interrupt pin I/O setting in rtl8367d DAL.
- 5. Add RTK API rtk_port_phyLinkDownPowerSaving_set/get.
- 6. Add RTK API rtk_port_phyGreenEthernet_set/get.
- 7. Add RTK API rtk_port_maxPacketLength_set/get.



Unmanaged Switch API Driver V1.4.2 Release Note

Revision	Release Date	Summary
1.4.2	2021/11/30	Error fix.
		New API added.

The package includes:

- Realtek Unmanaged Switch API Document.pdf Realtek Unmanaged Switch API
- Realtek Unmanaged Switch ProgrammingGuide.pdf Realtek Unmanaged Switch programming guide. 2.
- 3. API_Source - Realtek API and driver source code.
- 4. Supported chips:

•	1 N I L	ധാ	63N	ப

- RTL8364NB
- RTL8365MB-VC
- RTL8367RB-VB
- RTL8367SB
- RTL8363NB-VB
- RTL8364NB-VB
- RTL8367S
- RTL8366SC

RTL8363SC

- RTL8370MB
- RTL8310SR
- RTL8363SC-VB
- RTL8366SD
- RTL8367S-VB
- RTL8367RB-VC
- RTL8367SC
- RTL8365MB-VD

Changes

- Fix error #include in dal_rtl8367d_eee.c
- 2. Fix wrong number return when calling rtk_I2_limitLearningCnt_get in rtl8367d DAL
- Add MDI/MDIX API 3.
- Add GPIO API 4.
- Add PHY TestMode API 5.
- 23isecollilion Add RTCT support in rtl8367d DAL 6.



Unmanaged Switch API Driver V1.4.1 Release Note

Revision	Release Date	Summary	
1.4.1	2021/08/11	New APIs added & parameter update	
		Fiber 2.5G support	

The package includes:

- 1. Realtek Unmanaged Switch API Document.pdf Realtek Unmanaged Switch API
- 2. Realtek_Unmanaged_Switch_ProgrammingGuide.pdf Realtek Unmanaged Switch programming guide.
- 3. API_Source Realtek API and driver source code.
- 4. Supported chips:

•	חדו	റാ	63NB
-	\mathbf{H}	××	n 3111113
•	1 \ 1 L		OJIND

- RTL8364NB
- RTL8365MB-VC
- RTL8367RB-VB
- RTL8367SB
- RTL8363NB-VB
- RTL8364NB-VB
- RTL8367S
- RTL8366SC

RTL8363SC

- RTL8370MB
- RTL8310SR
- RTL8363SC-VB
- RTL8366SD
- RTL8367S-VB
- RTL8367RB-VB
- RTL8367SC
- RTL8365MB-VD

Changes

- 1. Add Fiber 2.5G support in rtl8367d DAL.
- 2. Add RGMII mode support in API rtk_port_phyComboPortMedia_set in rtl8367d DAL.
- 3. Add API rtk_port_fiberAbility_set / rtk_port_fiberAbility_get in rtl8367d DAL.
- 4. Update HSGMII/SGMII/Fiber parameter in rtl8367d DAL for better compatibility.
- 5. Remove Green Ethernet support in rtl8367d DAL.
- 6. Turn off auto-nego ability when user forces Fiber to 1G in rtl8367c DAL.

Switch Product Page 6 / 7 Rev. 1.4.3



Unmanaged Switch API Driver V1.4.0 Release Note

Revision	Release Date	Summary
1.4.0	2020/06/11	1. First Release

The package includes:

- Realtek_Unmanaged_Switch_API_Document.pdf Realtek Unmanaged Switch API 1.
- 2. Realtek_Unmanaged_Switch_ProgrammingGuide.pdf - Realtek Unmanaged Switch programming guide.
- 3. API_Source - Realtek API and driver source code.
- 4. Supported chips:

RTI	8363NB

- RTL8364NB
- RTL8365MB-VC
- RTL8367RB-VB
- RTL8367SB
- RTL8363NB-VB
- RTL8364NB-VB
- RTL8367S
- RTL8366SC

RTL8363SC

- RTL8370MB
- RTL8310SR
- RTL8363SC-VB
- RTL8366SD
- RTL8367S-VB
- RTL8367RB-VB
- RTL8367SC
- aise confidence in the confidence of the confide RTL8365MB-VD

Changes

1. First Release

Switch Product Rev. 1.4.3 Page 7 / 7