# LANDSCAPE SUPERINTENDENT

AND MAINTENANCE PROFESSIONAL

LSMP is focusing on Sprayers in an upcoming

# **EQUIPMENT REVIEW**

You are Invited to Participate in this Free Editorial Section

To include your product in this section, please send an email to:

## Ishield@landscapeonline.com

with "February Equipment Review" in the subject heading. Provide the following information inside the body of the email (not attached as a word document)

Manufacturer:

Model No:

Engine:

Nozzle:

Pump:

Tank Capacity:

Dimensions:

**Special Features:** 

Warranty:

Cost:

Include a high resolution tiff or jpeg photo (at least 300 dpi or a minimum of 2 MB in size.) Do not send web thumbnails.

To secure your position please send the information **A.S.A.P.** 

Contact: Larry Shield, Product Editor Ishield@landscapeonline.com (714) 979-5276 x125

**PGMS** 

In an exclusive industry alliance, the Professional Grounds Management Society (PGMS) has officially endorsed

Landscape Superintendent and Maintenance Professional (LSMP) magazine based on its Reach, Readership and Content.

## L BPA WORLDWIDE

### **About LSMP:**

- LSMP is the only publication targeting the Institutional Groundskeeper and Landscape Facilities Manager nationwide.
- LSMP is the only publication officially endorsed by the Professional Grounds Management Society (PGMS).
- 73% of LSMP readers are responsible for more than 50 acres and 29.6% are responsible for more than 250 acres.

## Send us your Product Info!

Send us your newest product photo and specifications for this Equipment Review



#### A.M. Leonard

Manufacturer: King's Service Model No: KS1P45

Engine: 5 hp Honda, 10.5 GPM, 560 psi Nozzle: Trigger spray gun included Pump: Udor diaphragm pump Tank Capacity: 100 gallons Special Features: Adjustable pressure, jet agitation. 50 feet of 3/8 inch hose included. No rust heavy duty aluminum frames. Sprays 30 to 40

feet.Warranty: One year warranty on all components. Three year warranty on poly tank. Two years warranty on Honda engine. Five year warranty on frame.

Cost: \$2,091.89