LANDSCAPE SUPERINTENDENT

AND MAINTENANCE PROFESSIONAL

LSMP is focusing on Spreaders & Top Dressers in an upcoming

EQUIPMENT REVIEW

You are Invited to Participate in this Free Editorial Section

To include your product in this section, please send an email to:

Ishield@landscapeonline.com

with "June Equipment Review" in the subject heading. Provide the following information inside the body of the email (not attached as a word document)

Manufacturer:

Model No .:

Engine & Horsepower:

Hopper Capacity:

Hopper Material:

Size:

Speed:

Accessories:

Special Features:

Warranty:

Cost:

Include a high resolution tiff or jpeg photo (at least 300 dpi or a minimum of 2 MB in size.) Do not send web thumbnails.

To secure your position please send the information A.S.A.P.

Contact: Larry Shield, Product Editor Ishield@landscapeonline.com

(714) 979-5276 x125



In an exclusive industry alliance, the Professional Grounds Management Society (PGMS) has officially endorsed

Landscape Superintendent and Maintenance Professional (LSMP) magazine based on its Reach, Readership and Content.

t. BPA

About LSMP:

- LSMP is the only publication targeting the Institutional Groundskeeper and Landscape Facilities Manager nationwide.
- LSMP is the only publication officially endorsed by the Professional Grounds Management Society (PGMS).
- 73% of LSMP readers are responsible for more than 50 acres and 29.6% are responsible for more than 250 acres.

Send us your Product Info!

Send us your newest product photo and specifications for this Equipment Review



Earth & Turf Products, LLC

Model No.: 320 MultiSpread™
Topdresser • Engine & Horsepower: Pull-type, Requires Tractor 20
HP or larger • Hopper Capacity: 26
Cu. ft. (Struck Level)

- Hopper Material: 12 Gauge Steel
- Size: 31" W x 20" Deep x 74" L
- Speed: 3-7 mph Accessories: Adjustable Wing Kit for Rear Shield,

Loading Chute, Light Material Sides • Special Features: Two-Wheel Ground Drive, Multi-directional Beater, 26-12.00-12 Turf Tires • Warranty: 2 yrs. (Material Defects & Workmanship) • Cost: \$4,700 Base