



Technician Assigned To
Deonardo Jimenez

Due Date
03/19/2026

Status
Open

Priority
High

Work Order Information

Assigned By: **Arno Utegg**
Assigned To: **Argenis Brito**

Date Created On
03/19/26

Last Updated

Date Completed On
03/19/2026

03/19/26

Assigned PURfx Team Member:
Deonardo Jimenez
Jorge Sanchez

LCBR Requested By

Location
La Cabana Beach Resort and Casino

Address
J.E. Irausquin Blvd 250, Oranjestad, Aruba

Task Description

LCBR Location & Service Work Required: Perform repairs on the Reymisa water level control system located at Cooling Tower B in the South chiller area.

Parts Used & Costs

Part Numbers: 156148-434
Quantity: One (1) ½" x4" sch 80 PVC nipple
One (1) ½" Galvanized conduit hubs

Labor Time	Additional Cost	Labor Cost	Total Cost
6 hours	\$0.00	\$0.00	\$0.00

Tasks

Service Type
Corrective Support

System Affected Mechanical

Root Cause Identified. (Upload pictures if available)

Findings/Actions performed. (upload pictures if available)

Additional Works Required? No

Define Required jobs?

Time Check in: 9:am

Time Check out: 12:PM

La Cabana Employee/Manager Service Requested By: (Printed Name)

Images

La Cabana Manager Service Completion Signature: