

Nomad Connect 2022.2

Release Notes

22nd of July 2022

Author	Ben Turner
Issue number	2022.2
Number of pages	5

Document control

Version	Version date	Summary of edits	Created By	Approved By
1	22.07.2022	First version of the document	Ben Turner	Julia Frick

The information in this document is subject to change without notice and should not be construed as a commitment by Nomad Digital Ltd. While reasonable precautions have been taken, Nomad Digital Ltd assumes no responsibility or liability for technical inaccuracies or typographical errors that may appear in this document. Nomad Digital Ltd reserves the right to revise this publication without obligation to provide notification of such revisions.

Features

Key	Summary:
RD-7405	A new feature called Lite User Experience has been delivered. The feature has been designed to throttle heavy consumers (downloads, streaming, ...) when latency went up, to allow new and smaller sessions to compete for available resources. The algorithm was developed to work as independent as possible from all other tools and will just keep an eye on the average latency. When average latency goes up, heavy users will be throttled to the average throughput of all users and so allowing to free up resources for the smaller users. Lite User Experience is part of MAR3 Captive Portal API
RD-9060	Added a new feature to be able to enable/disable floating IP. This is part of the Redundancy solution. • Availability of the floating IP address on the network can be made dependent on a condition file. • Can be used by other devices (e.g. Eltec and Westermo APs) to make a WiFi network available or not • Floating IP can be assigned to a certain CCU in the consist and will fail-over when that CCU disappears from the network
RD-9406	Developed a new feature called Stream Throttling, which allows us to throttle certain tagged streams. The following parameters are configurable: • throughput • throttling level per service class The configured throttling will override any service-level applied throttling already in place. This feature is reliant on 3rd party software to do the tagging.
RD-9422	Implemented a change to consist layout algorithm in OBN to support layouts starting with Intermediate car (as opposed to Brain car). This feature is being used by NMS

Defects

Key	Summary:
RD-9588	An issue was resolved regarding configuration problems IP addresses in the DHCP pool block.
RD-9536	An issue has been resolved where the Passive scanning service was not connecting to the MQTT bus properly. This only happened on first boot but has now been resolved.
RD-9504	There was an issue where the GPS reflector service was not starting on boot. This was due to a race condition but has now been resolved.
RD-9477	Redundancy: docker health check was not working with the new Redundancy solution as before (documentation). This has been resolved. This functionality is required for the Portal failover feature.