

Nomad Connect 2022.4

Release Notes

16th of Jan 2023

Author	Ben Turner
Issue number	2022.4
Number of pages	5

Document control

Version	Version date	Summary of edits	Created By	Approved By
1	06.01.2023	First version of the document	Ben Turner	Julia Frick

The information in this document is subject to change without notice and should not be construed as a commitment by Nomad Digital Ltd. While reasonable precautions have been taken, Nomad Digital Ltd assumes no responsibility or liability for technical inaccuracies or typographical errors that may appear in this document. Nomad Digital Ltd reserves the right to revise this publication without obligation to provide notification of such revisions.

Features

Key	Summary:
RD-7494	Added a feature to Nomad Connect to allow modem/sim APN configuration to be done automatically, based on a list of well-known APNs per country. The lookup of the relevant APN is done based on the operator code of the network that the modem is connected to.
RD-9324	Update of the autologin documentation for the DevOps team.
RD-9360	Enhancement of the Nomad Connect logrotate functionality to ensure that projects can configure custom blocks of logrotate rules.
RD-9411	Feature to ensure that the version of Nomad Connect is easily visible to support personnel connecting to the on-board CCU.
RD-9535	ospf_routing has been renamed to quagga: the module now supports both OSPF and PIM, and uses the zebra daemon underlying. This is needed for OBIS integration.
RD-9625	Upgrade of the Nomad Connect CDC infrastructure to support Debian 11 instead of Ubuntu. This ensures that the CCU and CDC operating system is brought in-line and both now uses Debian.
RD-9680	TGVM: OBN support for the 95x train type.
RD-9792	Replacement of MAR3 Ruby command-line tools with Python equivalents.
RD-9845	Addition of sudo module to Nomad Connect. This allows us to give specific users specific sudo rights to execute particular commands. This feature makes it possible to give restricted access to non-Nomad staff for commissioning or testing. For security reasons, SSH key still required for those users. This needs to be setup as per standard process.

Defects

Key	Summary:
RD-9910	A bug in the Direct Connect code prevented the system from working in this mode in combination with bridge devices. This has been resolved.
RD-9904	Under certain circumstances, disabling modems by configuration did not work.
RD-9896	When powercycling a modem, the engineering pages tx/rx averages were giving negative values due to rolling averages being wrong. These values are now reset when a modem does the same.

<u>RD-9876</u>	Embedded docker containers were not able to access the internet due to misconfigured default firewall rules.
<u>RD-9855</u>	Under certain circumstances, the OBN application showed signs of a memory leak, this has been resolved.
<u>RD-9850</u>	The number of devices connected to the on-board wifi was sometimes being misrepresented due to underlying linux neighbours tables working in an unexpected way.
<u>RD-9798</u>	Bug that was causing a conflict between MAR3 GPS-based SIM switching actions and startup actions on the 5001 CCU, causing the selected SIM card to sometimes be out of sync.
<u>RD-9622</u>	Critical security updates for the dpkg system on Debian linux.
<u>RD-9621</u>	Critical security updates for the openldap system on Debian linux.
<u>RD-9620</u>	Critical security updates for the expat system on Debian linux.
<u>RD-9619</u>	Critical security updates for the nss system on Debian linux.
<u>RD-9618</u>	Critical security updates for the openssl system on Debian linux.
<u>RD-9617</u>	Critical security updates for the libx11 system on Debian linux.
<u>RD-9616</u>	Critical security updates for the lz4 system on Debian linux.
<u>RD-9615</u>	Critical security updates for the bind9 system on Debian linux.