

# Nomad Connect 2023.3

## Release Notes

6<sup>th</sup> of November 2023

---

|                        |            |
|------------------------|------------|
| <b>Author</b>          | Ben Turner |
| <b>Issue number</b>    | 2023.3     |
| <b>Number of pages</b> | 4          |

## Document control

---

| Version | Version date | Summary of edits              | Created By | Approved By    |
|---------|--------------|-------------------------------|------------|----------------|
| 1       | 06.11.2023   | First version of the document | Ben Turner | Dieter Termote |

*The information in this document is subject to change without notice and should not be construed as a commitment by Nomad Digital Ltd. While reasonable precautions have been taken, Nomad Digital Ltd assumes no responsibility or liability for technical inaccuracies or typographical errors that may appear in this document. Nomad Digital Ltd reserves the right to revise this publication without obligation to provide notification of such revisions.*

## Features

| Key                      | Summary:                                                                                                                                                                                                                                                                                                                                               |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">RD-8773</a>  | A new command has been added to the OBN command line options called 'obn update all '. This allows for updating all switches and access points in a one-shot way rather than having to manually update all devices one by one.                                                                                                                         |
| <a href="#">RD-9916</a>  | Nomad Connect now supports new kernel-based packet switching functionality called MAR5, which is an enhancement to our existing MAR3 platform and has been developed to greatly increase IP packet handling performance.                                                                                                                               |
| <a href="#">RD-9919</a>  | Support for the new 4600v3 CCU has been added to Nomad Connect. This includes support for the new Telit FN990 5G modem.                                                                                                                                                                                                                                |
| <a href="#">RD-9920</a>  | Support for the new 5001c CCU has been added to Nomad Connect. This includes support for the new Telit FN990 5G modem.                                                                                                                                                                                                                                 |
| <a href="#">RD-9925</a>  | Support for the Westermo IBEX-1510 has been added to Nomad Connect OBN.                                                                                                                                                                                                                                                                                |
| <a href="#">RD-10115</a> | Nomad Connect 2023.3 is the first Nomad Connect that is based on Debian 12 OS.                                                                                                                                                                                                                                                                         |
| <a href="#">RD-10116</a> | A new Debian12 base image is available for use in 2023.3+ versions of Nomad Connect.                                                                                                                                                                                                                                                                   |
| <a href="#">RD-10175</a> | The base_system::deb10_var_tmp_partition_size variable was renamed to base_system::var_tmp_partition_size and the default value increased to 1GB to allow kernel updates (initramfs created in /var/tmp). The base_system::deb10_var_lib_systemd_partition_size variable was renamed to base_system::var_lib_systemd_partition_size and kept at 300MB. |
| <a href="#">RD-10195</a> | The caching_dns module needs to be reconfigured for this release. The DNS configuration has been modified to provide a unified approach for all projects.<br>The configuration changes are mandatory or DNS will fail after the upgrade.                                                                                                               |
| <a href="#">RD-10234</a> | A remote upgrade procedure has been foreseen for migration from Debian10 to Debian12.                                                                                                                                                                                                                                                                  |
| <a href="#">RD-10387</a> | The mar3 marcli command-line tool has been updated to allow for additional 5G output when a modem is using 5G networks.                                                                                                                                                                                                                                |
| <a href="#">RD-10393</a> | MAR3 now optionally supports specific backoff intervals when connecting modems to the network.                                                                                                                                                                                                                                                         |
| <a href="#">RD-10617</a> | The config shown below, typically found in hieradata/common.yaml will need the password hash re-generated when moving to Debian 12:<br>user:<br>developer:                                                                                                                                                                                             |

|                          |                                                                                                                                |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------|
|                          | ensure: "present"<br>password: "<debian12_password_hash>"<br>purge_ssh_keys: true<br>home: "/home/developer"                   |
| <a href="#">RD-10668</a> | The remote upgrade software for Telit modems has been updated to provide support for the new Telit FN990 modems (A28 and A40). |

## Defects

| Key                      | Summary:                                                                                                                                                                                                                                                                |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">RD-10694</a> | nd-modems component now has Python components added that allow for AT ports to be missing from ModemManagaer but still successfully send/receive AT data. CFUN getter/setter also moved from mar3-frontend component into nd-modems. nd-modems should be all automatic, |
| <a href="#">RD-10445</a> | A rare condition in the mar3-server was causing an OutOfMemory error, in turn causing connectivity to fail to CCUs. This has been resolved.                                                                                                                             |
| <a href="#">RD-10245</a> | Under certain circumstances, the tags in the /.snapshot/state file were not being restored properly on rollback. This has been fixed.                                                                                                                                   |

**Note! This release was only tested on the new Platforms: 5001c and 4600v3.**