

Nomad Connect 2024.2

Release Notes

1st July 2024

Author	Dieter Termote
Issue number	2024.2
Number of pages	5

Document control

Version	Version date	Summary of edits	Created By	Approved By
1	1.07.2024	First version of the document	Dieter Termote	Ben Turner

The information in this document is subject to change without notice and should not be construed as a commitment by Nomad Digital Ltd. While reasonable precautions have been taken, Nomad Digital Ltd assumes no responsibility or liability for technical inaccuracies or typographical errors that may appear in this document. Nomad Digital Ltd reserves the right to revise this publication without obligation to provide notification of such revisions.

What's new – Key changes

This Nomad Connect release includes:

- New Features
 - Update Wazuh agent for Debian 12
 - Correct logging of 5G bands (n77 and n78)
 - Updated NC control to allow for band selection in lab.
- HW Support
 - Support cellular Modem – MC7421 = CAT7 modem to replace the EOL MC7455
 - Support cellular Modem – LM960 in 4600-2.
 - 5001C CCU - cPCI-A3535ND2 (NMID1057) : fixed some critical issues found in Q1. All projects with this CPU blade must use NC 2024.2 AND BIOS version 1.02.10ND01 (or later).
- Regular maintenance and security updates : Bug fixes & security patches.

Features

Key	Release Notes
RD-10064	Nomad Connect now supports the MC7421 modem.
RD-11119	In order to reduce the load on the NMS, the OBN consist messages will be spread out over time between CCUs. Instead of each CCU publishing their message at 00, 05, 10 minutes, they will be published at 5, 10, 15 etc. minutes after CCU boot time.
RD-11162	Further work was done to ensure that Nomad Connect can correctly log which 5G bands are being used by the modems, if any, along with all the necessary band information.
RD-11166	The LM960A18 modem is now officially supported by Nomad Connect.
RD-11169	The Nomad Connect fallback_dns module now supports literal configuration files, as requested by DevOps.
RD-11196	Nomad Connect now provides basic support for the R2010 CCU. Full integration of the CCU will be done in Nomad Connect 2024.3.
RD-11224	A number of MAC prefixes were added to the known list of OBN prefixes for Eltec Cybox APs.
RD-11245	Wazuh client agent version 4.9.0 was integrated into Nomad Connect in order to provider proper support for Debian12. Port scans and Nessus signatures not yet reported.

Defects

The following defects were addressed in this release:

Key	Release Notes
RD-11264	A bug in the default Nomad Connect iptables rules was causing the captive portal not to work properly under certain conditions, this has been resolved.
RD-11253	Under certain data conditions, the engineering pages data collector would crash and stop feeding the pages with data. This has been resolved.
RD-11246	Nomad Connect was sometimes incorrectly reporting modems as using 5G bands when in fact they were using LTE bands. This has been fixed.
RD-11225	A bug in the media mounting scripts was causing existing partitions to be wiped out, this has been addressed.
RD-11203	Nomad Connect was using the wrong RTC clock module on the 5001c CCU, this has been rectified to ensure that the correct module is used.
RD-11198	Certain project-specific manifests with package repositories were still present in the nomad_connect repository, these have been removed and the possibility to manage this externally from hiera has been added.
RD-11178	Errors in the SSH daemon configuration file were causing a password prompt to be displaying for users connecting without a valid SSH key. This should never be the case as only key login is allowed. This has been rectified.
RD-11167	The lldp daemon was attempting to use lan1 on the 3500 but this device does not exist: this has been replaced with lan0 instead for that CCU.
RD-11088	The nightly automatic update script was returning with an error in case no update was necessary. The script has been modified to indicate that "no update needed" is also a valid (normal) exit condition.
RD-11082	The nd-telemetry component was logging a lot of unnecessary messages to the log files - this has been fixed.
RD-11081	The nd-action component was logging a lot of unnecessary messages to the log files - this has been fixed.

HW Platforms tested in this release

All formal testing was completed on dedicated QA benches as follows:

CCU	Card / Storage	Modem / mPCIe	Layer 3
R5001c	SSD	FN990A40 FN990A28 M8 GPS	10GB Oring Switch Eltec NAP-1022-2GP-M12X NM31 Switch
4600v3	CFAST	FN990A40 FN990A28 EM7455 EM7421 Compex 600	Oring Switch Eltec NAP-1022-2GP-M12X NM31 Switch
4600v2	CFAST	EM7455 MC7455 LM940 Onboard GPS	Oring Switch Cybox AP1
R5001B	MicroSD	G25A G227 MC7455 LM940 M8 GPS 7P GPS	Eltec Switch Cybox AP2 x2 G25A G227
4600v1	MicroSD	MC7455 Onboard GPS	MEN NL34 Cybox AP1
B2010	CFAST	MC7455 EM7455 Onboard GPS	
R3500	SSD	MC7455 M8 GPS 7P GPS	SATA Blades G501R F22P12