```
Last login: Mon Feb  3 14:20:10 on console
jamesxxx1997de-MacBook-Air:~ jamesxxx1997$ cd /Volumes/WEPE/lenovo-miix-520-hackintosh-CLOVER-2.0/keyboard
-bash: cd: /Volumes/WEPE/lenovo-miix-520-hackintosh-CLOVER-2.0/keyboard: No such file or directory
jamesxxx1997de-MacBook-Air:~ jamesxxx1997$ log show --last 1d | grep "Wake reason"
2020-02-02 13:27:06.943980+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI XHC
2020-02-02 13:27:06.943988+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI XHC
2020-02-02 17:15:04.980585+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-02 17:15:04.980592+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-02 19:16:15.567488+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-02 19:16:15.567496+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 07:17:56.295728+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI XHC
2020-02-03 07:17:56.295735+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI XHC
2020-02-03 09:27:49.078568+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 09:27:49.078575+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:22:45.860238+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:22:45.860245+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:23:32.924025+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:23:32.924032+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:24:18.456892+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:24:18.456899+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:25:05.388915+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:25:05.388922+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:25:51.362137+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:25:51.362144+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:26:39.121081+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:26:39.121088+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:27:26.031031+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:27:26.031038+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:28:12.301452+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:28:12.301459+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:28:58.313844+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:28:58.313851+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:29:44.481657+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:29:44.481665+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:30:31.324659+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:30:31.324666+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:31:17.666781+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:31:17.666788+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:32:04.125716+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:32:04.125723+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:32:50.388155+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:32:50.388162+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:33:36.420553+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:33:36.420560+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:34:23.602531+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:34:23.602538+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:35:09.311317+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:35:09.311324+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:35:55.135278+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:35:55.135285+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:36:42.205364+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:36:42.205371+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:37:29.009459+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:37:29.009466+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:38:15.518767+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:38:15.518774+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:39:01.872073+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:39:01.872080+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:39:48.989778+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:39:48.989786+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:40:35.308272+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:40:35.308279+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:41:21.921944+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:41:21.921951+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:42:08.307634+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:42:08.307641+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:42:55.252959+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:42:55.252966+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:43:42.286927+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:43:42.286934+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:44:28.423745+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:44:28.423752+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:45:14.591976+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:45:14.591983+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:46:01.315349+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:46:01.315356+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:46:47.763060+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:46:47.763067+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:47:34.956231+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:47:34.956238+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:48:21.208815+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:48:21.208822+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:49:08.008184+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:49:08.008191+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:49:54.082459+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:49:54.082466+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:50:40.788399+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:50:40.788407+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:51:27.433972+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:51:27.433979+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:52:13.667476+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:52:13.667483+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:53:00.363473+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:53:00.363481+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:53:46.707021+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:53:46.707029+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:54:33.963809+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:54:33.963816+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:55:20.523934+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:55:20.523941+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:56:06.896535+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:56:06.896542+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:56:53.322757+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:56:53.322764+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:57:39.265218+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:57:39.265225+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:58:26.809182+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:58:26.809189+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:59:12.332698+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:59:12.332705+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:59:59.929684+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 11:59:59.929691+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:00:46.047698+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:00:46.047705+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:01:32.643550+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:01:32.643557+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:02:19.323552+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:02:19.323559+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:03:05.847360+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:03:05.847367+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:03:52.988886+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:03:52.988893+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:04:39.768915+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:04:39.768922+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:05:26.656972+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:05:26.656979+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:06:12.973501+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:06:12.973509+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:07:00.228234+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:07:00.228242+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:07:47.887090+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:07:47.887097+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:08:33.790279+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:08:33.790286+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:09:20.865650+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:09:20.865657+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:10:07.311855+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:10:07.311862+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:10:53.066399+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:10:53.066406+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:11:40.940897+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:11:40.940904+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:12:26.300099+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:12:26.300106+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:13:14.059626+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:13:14.059633+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:14:00.235801+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:14:00.235809+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:14:46.284885+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:14:46.284892+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:15:32.525611+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:15:32.525618+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:16:19.869371+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:16:19.869377+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:17:06.396887+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:17:06.396894+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:17:52.708815+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:17:52.708822+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:18:40.068508+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:18:40.068514+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:19:27.142756+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:19:27.142763+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:20:13.821507+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:20:13.821514+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:21:00.310201+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:21:00.310209+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:21:46.208776+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:21:46.208783+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:22:32.671679+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:22:32.671686+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:23:20.092471+0800 0x74       Default     0x0                  0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
```

```
2020-02-03 12:23:20.092478+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:24:06.930000+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:24:06.930009+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:24:53.253571+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:24:53.253578+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:25:39.477582+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:25:39.477590+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:26:25.310666+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:26:25.310673+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:27:12.538497+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:27:12.538504+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:27:58.574668+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:27:58.574675+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:28:46.014062+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:28:46.014069+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:29:32.592147+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:29:32.592155+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:30:19.172373+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:30:19.172380+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:31:05.762338+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:31:05.762339+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:31:52.428888+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:31:52.428895+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:32:39.853008+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:32:39.853015+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:33:25.322020+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:33:25.322027+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:34:12.775543+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:34:12.775550+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:34:59.898853+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:34:59.898860+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:35:45.268941+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:35:45.268948+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:36:32.426438+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:36:32.426445+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:37:18.395965+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:37:18.395972+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:38:04.625185+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:38:04.625192+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:38:50.096647+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:38:50.096654+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:39:36.772317+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:39:36.772324+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:40:23.849976+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:40:23.849983+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:41:11.048388+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:41:11.048395+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:41:58.019445+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:41:58.019452+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:42:43.733773+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:42:43.733780+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:43:30.695671+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:43:30.695678+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:44:17.785433+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:44:17.785440+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:45:04.907251+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:45:04.907258+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:45:50.742322+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:45:50.742329+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:46:37.989324+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:46:37.989331+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:47:24.580138+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:47:24.580145+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:48:11.768175+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:48:11.768182+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:48:57.658743+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:48:57.658750+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:49:43.812829+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:49:43.812836+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:50:30.685988+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:50:30.685995+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:51:16.711248+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:51:16.711255+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:52:03.449995+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:52:03.450002+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:52:49.801748+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:52:49.801754+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:53:36.334874+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:53:36.334881+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:54:24.256771+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:54:24.256778+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:55:11.021221+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:55:11.021229+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:55:57.628232+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:55:57.628239+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:56:43.656282+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:56:43.656289+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:57:30.421297+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:57:30.421304+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:58:16.378352+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:58:16.378359+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:59:03.704603+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:59:03.704610+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:59:49.842069+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 12:59:49.842077+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:00:36.533439+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:00:36.533446+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:01:22.760359+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:01:22.760366+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:02:09.653791+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:02:09.653798+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:02:57.031289+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:02:57.031296+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:03:43.282802+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:03:43.282809+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:04:29.628108+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:04:29.628115+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:05:15.818435+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:05:15.818442+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:06:02.652656+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:06:02.652663+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:06:49.854010+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:06:49.854017+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:07:36.691405+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:07:36.691412+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:08:22.147292+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:08:22.147299+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:09:09.951127+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:09:09.951135+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:09:55.950739+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:09:55.950747+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:10:42.610238+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:10:42.610245+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:11:29.535004+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:11:29.535006+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:12:16.304052+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:12:16.304059+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:13:02.502207+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:13:02.502214+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:13:48.782866+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:13:48.782873+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:14:35.672408+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:14:35.672415+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:15:22.660658+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:15:22.660665+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:15:35.228212+0800 0x2ec50    Default     0x0                 0     0    kernel: (AppleTopCaseHIDEventDriver) [HID] [ATC] AppleDeviceManagemantHIDEventService::processWakeReason Wake reason: Host (0x01)
2020-02-03 13:16:08.868759+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:16:08.868766+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:16:21.235169+0800 0x2f010    Default     0x0                 0     0    kernel: (AppleTopCaseHIDEventDriver) [HID] [ATC] AppleDeviceManagemantHIDEventService::processWakeReason Wake reason: Host (0x01)
2020-02-03 13:16:55.781775+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:16:55.781782+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:17:08.177945+0800 0x2f3af    Default     0x0                 0     0    kernel: (AppleTopCaseHIDEventDriver) [HID] [ATC] AppleDeviceManagemantHIDEventService::processWakeReason Wake reason: Host (0x01)
2020-02-03 13:17:43.275392+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:17:43.275399+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:17:55.105415+0800 0x2f75b    Default     0x0                 0     0    kernel: (AppleTopCaseHIDEventDriver) [HID] [ATC] AppleDeviceManagemantHIDEventService::processWakeReason Wake reason: Host (0x01)
2020-02-03 13:21:07.588004+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:21:07.588011+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:21:19.274352+0800 0x30338    Default     0x0                 0     0    kernel: (AppleTopCaseHIDEventDriver) [HID] [ATC] AppleDeviceManagemantHIDEventService::processWakeReason Wake reason: Host (0x01)
2020-02-03 13:36:17.278441+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:36:17.278448+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: GLAN XDCI
2020-02-03 13:36:28.544579+0800 0x31285    Default     0x0                 0     0    kernel: (AppleTopCaseHIDEventDriver) [HID] [ATC] AppleDeviceManagemantHIDEventService::processWakeReason Wake reason: Host (0x01)
2020-02-03 14:20:13.102501+0800 0xadb      Default     0x0                 0     0    kernel: (AppleTopCaseHIDEventDriver) [HID] [ATC] AppleDeviceManagemantHIDEventService::processWakeReason Wake reason: Host (0x01)
2020-02-03 14:50:50.984646+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 14:50:50.984646+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 15:28:20.853482+0800 0x81c9     Default     0x0                 0     0    kernel: (AppleTopCaseHIDEventDriver) [HID] [ATC] AppleDeviceManagemantHIDEventService::processWakeReason Wake reason: Host (0x01)
2020-02-03 15:29:59.459934+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 15:29:59.459935+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 16:29:31.347597+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 16:29:31.347598+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 17:27:45.675187+0800 0x8e7f     Default     0x0                 0     0    kernel: (AppleTopCaseHIDEventDriver) [HID] [ATC] AppleDeviceManagemantHIDEventService::processWakeReason Wake reason: Host (0x01)
2020-02-03 17:29:49.092453+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 17:29:49.092454+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 18:05:54.200905+0800 0x943e     Default     0x0                 0     0    kernel: (AppleTopCaseHIDEventDriver) [HID] [ATC] AppleDeviceManagemantHIDEventService::processWakeReason Wake reason: Host (0x01)
2020-02-03 18:07:55.331531+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 18:07:55.331532+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 18:41:45.885915+0800 0x997b     Default     0x0                 0     0    kernel: (AppleTopCaseHIDEventDriver) [HID] [ATC] AppleDeviceManagemantHIDEventService::processWakeReason Wake reason: Host (0x01)
2020-02-03 18:44:51.170157+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 18:44:51.170159+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 19:22:21.222492+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 19:22:21.222493+0800 0x74       Default     0x0                 0     0    kernel: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC GLAN XDCI XHC (Alarm)
2020-02-03 19:56:46.173879+0800 0xa3e0     Default     0x0                 0     0    kernel: (AppleTopCaseHIDEventDriver) [HID] [ATC] AppleDeviceManagemantHIDEventService::processWakeReason Wake reason: Host (0x01)
```