

Tempus Stylus Known Problems and Solutions

Product Version 26.10
May 2026

© 2015-2026 Cadence Design Systems, Inc. All rights reserved.
Printed in the United States of America.

Cadence Design Systems, Inc. (Cadence), 2655 Seely Ave., San Jose, CA 95134, USA.

Trademarks: Trademarks and service marks of Cadence Design Systems, Inc. (Cadence) contained in this document are attributed to Cadence with the appropriate symbol. For queries regarding Cadence's trademarks, contact the corporate legal department at the address shown above or call 1-800-862-4522.

All other trademarks are the property of their respective holders.

Restricted Print Permission: This publication is protected by copyright law and international treaties and contains trade secrets and proprietary information owned by Cadence. Unauthorized reproduction or distribution of this publication, or any portion of it, may result in civil and criminal penalties. Except as expressly permitted below, this publication may not be copied, reproduced, modified, published, uploaded, posted, transmitted, or distributed in any way, including automated processes, training or services involving a large language model, foundation model, deep machine learning, generative artificial intelligence, or any other similar process or technology, without prior written permission from Cadence. Unless otherwise agreed to by Cadence in writing, customers are granted permission to print one (1) hard copy of this publication subject to the following conditions:

1. The publication may be used solely for personal, informational, and noncommercial purposes;
2. The publication may not be modified in any way;
3. Any copy of the publication or portion thereof must include all original copyright, trademark, and other proprietary notices and this permission statement; and
4. Cadence reserves the right to revoke this authorization at any time, and any such use shall be discontinued immediately upon written notice from Cadence.

Disclaimer: Information in this publication is subject to change without notice and does not represent a commitment on the part of Cadence. Except as may be explicitly set forth in such agreement, Cadence does not make, and expressly disclaims, any representations or warranties as to the completeness, accuracy or usefulness of the information contained in this document. Cadence does not warrant that use of such information will not infringe any third party rights, nor does Cadence assume any liability for damages or costs of any kind that may result from use of such information. Cadence is committed to using respectful language in our code and communications. We are also active in the removal and/or replacement of inappropriate language from existing content. This product documentation may however contain material that is no longer considered appropriate but still reflects long-standing industry terminology. Such content will be addressed at a time when the related software can be updated without end-user impact.

Restricted Rights: Use, duplication, or disclosure by the Government is subject to restrictions as set forth in FAR52.227-14 and DFAR252.227-7013 et seq. or its successor.

Contents

About This Manual	5
1	6
Base and SI Delay Analysis	6
Identified in Previous Releases	6
Solution	6
2	7
Timing Analysis	7
Identified in Previous Releases	7
Solution	8
3	9
Signal Integrity	9
Identified in Previous Releases	9
Solution	9
4	10
Distributed Static Timing Analysis	10
Identified in Previous Releases	10
Collection Commands not Supported in DSTA CUI	10
Legacy Features not Mapped to DSTA CUI	10
Solution	11
5	12
Signoff ECO	12
Identified in Previous Releases	12
Solution	12
6	13
Others	13
Identified in Previous Releases	13
Solution	13

About This Manual

This Known Problems and Solutions (KP&S) document describes important known issues for Tempus CUI and tells you how to solve or workaround these problems.

Base and SI Delay Analysis

Identified in Previous Releases

The following `set_instance_voltage` parameter is not mapped from Tempus legacy to Tempus CUI:

- `-pg_pin`

The following features are not mapped from Tempus legacy to Tempus CUI:

- The following legacy `update_delay_corner` parameters are not supported:
 - `-early_opcond <opcondName>`
 - `-early_opcond_library <libName>`
 - `-late_library_set <libSetName>`
 - `-late_opcond <opcondName>`
 - `-late_opcond_library <libName>`
 - `-library_set <libSetObj>`
 - `-opcond <opcondName>`
 - `-power_domain <powerDomainName>`
 - `-supply_set <supplySetName>`

Solution

You can use `eval_legacy` to run a legacy command in the legacy Tcl interpreter.

Timing Analysis

Identified in Previous Releases

- The `timing_path_based_epba_bounded_mode` attribute is not mapped from Tempus legacy to CUI.
- The following `set_path_group` command parameters are not mapped from legacy to Tempus DSTA CUI:
 - `-clock_from`
 - `-clock_to`
 - `-from`
 - `-name`
 - `-slack_adjustment`
 - `-through`
 - `-to`
- The following `merge_reports` command parameters are not mapped from legacy to Tempus DSTA CUI:
 - `-input_report_files`
 - `-max_paths`
 - `-nworst`
 - `-quiet`
 - `-type`
 - `-merge_type`
 - `-write_csv_file`
- The following `report_annotations` command parameters are not mapped from legacy to Tempus DSTA CUI:
 - `-ignore_floating_nets`

- `-ignore_tied_low_high_net_arcs`
- `-ignore_tied_low_high_nets`
- `-list_annotated`
- `-list_non_annotated`
- `-max_missing`
- `-missing_capacitances`
- `-missing_delays`
- `-missing_rc`
- `-missing_resistances`
- `-missing_spf`
- `-tcl_list`
- `-view`

Solution

You can use `eval_legacy` to run a legacy command in the legacy Tcl interpreter.

Signal Integrity

Identified in Previous Releases

The following `update_glitch` parameter is not mapped from Tempus legacy to DSTA CUI:

- `-effort`

The following features are not mapped from Tempus legacy to Tempus CUI:

- The following timing category attributes are not supported:
 - `timing_disable_backward_compatible_timing_derate_mode`
 - `timing_enable_etm_latch_thru_mode`
 - `timing_extract_model_backward_compatible_report_mode`
 - `timing_extract_model_enable_waveform_propagation`
 - `timing_extract_model_improved_waveform_cache`
 - `timing_extract_model_write_asymmetric_lvf`
 - `timing_path_based_maximum_time_limit`

Solution

You can use `eval_legacy` to run a legacy command in the legacy Tcl interpreter.

Distributed Static Timing Analysis

Identified in Previous Releases

Collection Commands not Supported in DSTA CUI

The DSTA CUI does not support the use of collection commands, such as, `get_pins`, `get_clocks`, with the `get_db` command. The use models, like `get_db [get_clocks]` or `get_db [get_pins]` may not work as expected.

Solution: You can specify objects, such as, pins, or clocks with the `get_db` command. The collection command support for `get_db` will be available in a future release.

Legacy Features not Mapped to DSTA CUI

The following features are not mapped from Tempus legacy to DSTA CUI:

- The `write_tcf` command is not supported.
- The following `read_power_rail_results` command parameters are not supported:
 - `-instances`
 - `-short_file`
 - `-suppress_message`
 - `-tile_thermal_config_file`
- The `set_lib_binding_by_voltage` command shows different `-help` parameters than the STA CUI command help.
- The `set_max_cap_per_freq_tran` command is supported in DSTA CUI, however, the `-help` shows an error that the command is not implemented.

The following features are not mapped from Tempus legacy to DSTA CUI:

- The `report_obj` command is not supported.
- The `get_common_ui_map get_global` command does not display the legacy CUI details.
- The following `read_design` parameters are not mapped to the `read_db` command:

- `-dynamic_view`
- `-hold_views`
- `-leakage_view`
- `-oaRef`
- `-setup_views`

Solution

You can use `eval_legacy` to run a legacy command in the legacy Tcl interpreter.

Signoff ECO

Identified in Previous Releases

The following feature is not mapped from Tempus legacy to Tempus CUI:

- `setBetaFeature` command

Solution

You can use `eval_legacy` to run a legacy command in the legacy Tcl interpreter.

Others

Identified in Previous Releases

The following features are not mapped from Tempus legacy to DSTA CUI:

- The `set_max_cap_per_freq_transition` command is not supported.
- The `read_ilm` command is supported in DSTA CUI. However, the command `-help` does not show up, the following error message is displayed:

```
**ERROR: (DSTA-1006): Command 'read_ilm' is not implemented.
```

The following features are not mapped from Tempus legacy to Tempus CUI:

- The `define_attribute -obj_type` parameter does not support `lib_pg_pin` option.
- The `read_design` and `read_db` command `-help` does not match.
- The `write_sdf` command `-help` does not match for Tempus legacy and CUI.
- The `sizeof_collection` command is not supported in `get_db` designs.
- The `read_lib -lef` command parameter is not supported.
- The `get_common_ui_map` command output for the following commands is not correct:
 - `get_analysis_view`
 - `get_constraint_mode`
 - `get_delay_corner`
 - `get_library_set`
 - `get_op_cond`

Solution

You can use `eval_legacy` to run a legacy command in the legacy Tcl interpreter.