Tri Axis Touch Probe / Tool Setter TATP 001

Specification Document

Application Area



Probe Moving Directions



Tool Touch Point



Casing Details



Mounting Hole



Machine Interface Details



Cable Protection System



Dimension with out Mounting Bracket



Touch signal Indication

