

REVISIONS				
E.C. NO.	REV.	DESCRIPTION	BY	DATE
	Α	DRAWING RELEASED	SH	1/09

NOTES:

- POSITION (MF09-595) AS SHOWN IN DRAWING, STIFFENER SHOULD BE LOCATED ON THE RIGHT SIDE OF THE ELEVATOR BELLCRANK, SO IT DOES NOT INTERFERE WITH LIMIT SWITCH.

- TRIMMING ON LOWER FORMER U10 AND TAILWHEEL FWD ENCLOSURE MAY BE NECESSARY.



TITAN AIRCRAFT SUPPLY 1419 STATE ROUTE 45 SOUTH AUSTINBURG, OHIO 44010

DETAIL NAME ELEVATOR BELLCRANK STIFFENER INSTALLATION SCALE 1/4"=1" PART NO. ASSEMBLY NAME

CHECKED

APPROVED

KORY B.

RI

DATE

DATE 7/7/09

6/26/09 PART NO. DRAWING NO. 05

DRAWING NO. BT51-09-INS-1807-A