

Print Name:

Kevin Flint

EMCOR, EMR BUILDING, OLDBURY

${\bf HEALTH~AND~SAFETY~RISK~ASSESSMENT~RECORD-NUMBER~\underline{RA007}}$

Site/Premis	· D · · · · · ·		Area/Section: EMR Building							
Work Activity: Hand Tools (Not Powered)					((/	
PERSONS AFFECTED					✓Yes ✓ No)	CLASSIFICATION		√Yes	✓ No
Employees					✓ ✓		Experienced		✓	
	Other Workers						Inexperienced	l	✓	
Public					✓		Disabled			✓
Comments: INEXPERIENCED OPERATIVES REQUIRE ADDITIONAL SUPERVISION										
HAZARD T					✓Yes ✓ No)			√Yes	✓ No
Physical Inju					√			g. Micro Organism)		✓
Health Hazai			✓		Natural (e.g.	Weather)		✓		
	SEE ALSO NOIS									
	s appropriate		1 .			- .				
Contact with	, , ,				Fire			Weather		
	b) Moving Materials				Explosion		Temperature			
	c) Moving Vehicles				Burns			Manual Handling		✓
	d) Fixed	Macl	ninery		Falls from Heights Lone Working					
Electrical:	a) Shock				Pressurised Systems Hand Tools				✓	
	b) Burns				Vibration Confined Spaces					
	c) Explo				Noise ✓ Restricted Access			/Egress		
Radiation:	a) Ultrav				Harmful Substa	ances		Power Tools	6	
Radiation.	b) Ionisi				Vermin	ances	'	Sharp Objects		✓
	c) Lasers	_			Particles		/	Posture		
C	c) Lasers	,			Tarticies		,	1 Ostule		
Comments:										
Likelihoo	d x Severity =	= Ris	sk Score. S	Score assumi	ng standard	con	trol measu	res overleaf are	implem	ented = 2
SIGNIFICA	NT RISK IDEN	ΓΙFΙΙ	ED:							
Eye Injuries,	Incorrect Tool Us	age, l	Incorrect Tool	s for Task, Noise	, Burns, Dust, Cu	ts, Al	brasions			
RELEVAN	T STATUTORY	PRO	VISIONS (AN	ND GUIDANCE	(Note: Standar	d Co	ntrol Measur	es must also be revie	wed and r	nade site
specific)			,		, , , , , , , , , , , , , , , , , , , ,					
	974, P.U.W.E.R.	1998.	Management	of Health, Safety	at Work Regs 19	99. C	Construction D	esign Management Re	egs 2007, F	P.P.E. Regs
	at Work Regs 198		J	, ,	Č			8		C
	IRED FOR TASI	K (tic				rol Measures over page making specific)				
Hard Hat			✓	Ear Protection			✓ Welding Helmet			
Safety Footw			✓	Goggles				Respirator (enter type	e)	
	High Vis Vest		✓	Overalls			Gloves (3)			
Gas Welding Goggles			Safety Spectacles			✓	Other (specify type)			
Circle Resid	lual Risk Score at	fter in	nplementatio	n of your additio	onal Control Me	asur	es (if any)			
					Risk Score = 1	A	Acceptable – ur	nlikely to cause first a	id case inju	ıry, risk to
Likelihood		Seve	rity of Injury		LOW	h	health, property or environmental damage.			
of					Risk Score = 2			likely to cause lost ti		
Harm	LOW 1		MED 2	HIGH 3	LOW	h	ealth, property	or environmental dar	nage. Wo	rk to be
					✓			competent person.		
	Possible first		ssible <3 day	Possible >3	Risk Score = 3			se serious injury, risk		
	aid case	lost	time injury,	day serious	LOW			damage. Control mea	sures and v	written
	injury,		minor	injury, major		n	nethod stateme	nt must be in place.		
	environmental	en	vironmental	environmental						
	damage		damage	damage						
Unlikely 1	1		2	3	Risk Score = 4			lost time injury, mind		
					MEDIUM			damage. Supervision,		easures and
								statement must be in		
Possible 2	2 ✓		4	6	Risk Score = 6			- revisit work procedu	ires to redu	ice this risk
	✓				HIGH	to	o a score of for	ır or below		
					D. 1.6			0.1		
Likely 3	3		6	9	Risk Score = 9			refer the operation to		
					HIGH			ne work must not proc		posed, an
						a	nernative meth	nod must be developed	J	
Signed:			-	Position in Con	npany: Ope	ratio	ns Director	Date	: 14-03	-13

Date of Review: 14-06-13

AGILE BUILDING SERVICES LIMITED – PROJECT SPECIFIC RISK ASSESSMENTS



EMCOR, EMR BUILDING, OLDBURY

No p	AILS OF CONTROL MEASURES ersons are to work with hand tools unless they have read this document iling the Risks associated with this operation	Is this control measure in place	Additional action required
1.	Tools provided by the employer must be assessed to ensure that they are fit for the purpose, the environment in which they are to be used and in good working condition.	√	
2.	Tools are required to be suitable for the purposes for which they will be used.	√	
3.	Eye protection is to be provided and used whenever work is being carried out for example; using cold chisels or any other tools where there is a risk of flying particles or pieces of tool breaking off.	√	
4.	Use of open bladed knives, screwdrivers and other sharp tools are to be carried and used so as not to cause injury to the user or others.	√	
5.	Insulated tools must be used where there is a possibility of live electrical work.	√	
6.	Management will monitor hand tools which can deteriorate with use, to ensure they are sharpened or replaced as necessary.	√	
7.	Ear protection to be worn, for activities creating noise levels above 80dB (A).	√	
8.	The user must carry out visual inspections of tools they are using and do not use any tools which are clearly defective.	√	
9.	Tools must not be carried in clothing pockets which could present a penetration/puncture hazard e.g. knife, pad saw.	√	
10.	Whenever using hacksaws/knives or other sharp cutting instruments, gloves must be worn.	√	
11.	Any cutting tools must be sharp in order to reduce the effort required when using the tool and thus eliminate the potential for blades breaking during use.	√	



EMCOR, EMR BUILDING, OLDBURY

Name:	Signature:	Date: